

# Vallabh Enterprises

**Regd. Office :** 401,shanti kutir,shivaji road,near thakur international school,kandivali(west) mumbai - 400067  
**Support :** | **W :** www.vallabhenterprises.com  
**E :** vallabhsecure@yahoo.co.in

<b>Service Status Details : VE15440</b>																									
<b>Priority :</b>	Low																								
<b>Created By :</b>	Admin - Apurva Vajaria																								
<b>Complaint Mob. No. :</b>	9869439970																								
<b>Technician Name :</b>	Atique Salmani		<b>Technician Mobile :</b>	8080922984																					
<b>Ticket Type :</b>	Complain	<b>Date &amp; Time :</b>	31-07-2025 10:28:22																						
<b>Vendor Details :</b>																									
Company Name/Client Name :	Eden Garden	Customer's Mobile :	9869439970	Name :	Rajesh Sir																				
<b>Address :</b>																									
Mumbai , , , , Maharashtra																									
<b>AMC Details :</b>																									
Expiry Date :	01-01-1970 05:30:00		Type :																						
<b>Product Name :</b>	Intercom																								
<b>Complain :</b>	4 lift intercom reinstallation need to do																								
<b>Technician Comment :</b>	A wing 1st lift connection done working with phone installation b wing line didn't get on lift metr room so need to new cabling boath wing. Approx 120 metr cat6 from 2nd floor to lift metr room .																								
<b>Complain Operator :</b>	Desktop - Apurva Vajaria																								
<b>Remark :</b>	A wing 1st lift connection done working with phone installation b wing line didn't get on lift metr room so need to new cabling boath wing. Approx 120 metr cat6 from 2nd floor to lift metr room .																								
<b>Status History :</b>	<table><thead><tr><th>Date Time</th><th>Technician Name</th><th>Status</th><th>Remark</th><th>Sign</th></tr></thead><tbody><tr><td>31-07-2025 03:55:11</td><td>Atique Salmani</td><td>Work Pending</td><td>A wing 1st lift connection done working with phone installation b wing line didn't get on lift metr room so need to new cabling boath wing. Approx 120 metr cat6 from 2nd floor to lift metr room .</td><td>Atique Salmani</td></tr><tr><td>31-07-2025 03:55:11</td><td>Atique Salmani</td><td>Work Pending</td><td>A wing 1st lift connection done working with phone installation b wing line didn't get on lift metr room so need to new cabling boath wing. Approx 120 metr cat6 from 2nd floor to lift metr room .</td><td>Atique Salmani</td></tr><tr><td>31-07-2025 10:28:27</td><td>Atique Salmani</td><td>New</td><td></td><td>-</td></tr></tbody></table>					Date Time	Technician Name	Status	Remark	Sign	31-07-2025 03:55:11	Atique Salmani	Work Pending	A wing 1st lift connection done working with phone installation b wing line didn't get on lift metr room so need to new cabling boath wing. Approx 120 metr cat6 from 2nd floor to lift metr room .	Atique Salmani	31-07-2025 03:55:11	Atique Salmani	Work Pending	A wing 1st lift connection done working with phone installation b wing line didn't get on lift metr room so need to new cabling boath wing. Approx 120 metr cat6 from 2nd floor to lift metr room .	Atique Salmani	31-07-2025 10:28:27	Atique Salmani	New		-
Date Time	Technician Name	Status	Remark	Sign																					
31-07-2025 03:55:11	Atique Salmani	Work Pending	A wing 1st lift connection done working with phone installation b wing line didn't get on lift metr room so need to new cabling boath wing. Approx 120 metr cat6 from 2nd floor to lift metr room .	Atique Salmani																					
31-07-2025 03:55:11	Atique Salmani	Work Pending	A wing 1st lift connection done working with phone installation b wing line didn't get on lift metr room so need to new cabling boath wing. Approx 120 metr cat6 from 2nd floor to lift metr room .	Atique Salmani																					
31-07-2025 10:28:27	Atique Salmani	New		-																					

Previous Complain History :			
	Date Time	Technician Name	Remark
	02-08-2025 01:19:04	PravinJagade	A wing tv off issue resolve done working ok.
	30-07-2025 10:42:32	Ravi Rajbhar	B wing intercom line ok instument issue need to change