


Vallabh Enterprises

Regd. Office : 401,shanti kutir,shivaji road,near thakur international school,kandivali(west) mumbai - 400067
Support : | W : www.vallabhenterprises.com
E : vallabhsecure@yahoo.co.in

Service Status Details : VE15561					
Priority :	Low				
Created By :	Admin - Apurva Vajaria				
Complaint Mob. No. :	9869439970				
Technician Name :	Atique Salmani		Technician Mobile :	8080922984	
Ticket Type :	Complain	Date & Time :	14-08-2025 11:27:13		
Vendor Details :					
Company Name/Client Name :	Eden Garden	Customer's Mobile :	9869439970	Name :	Rajesh Sir
Address :					
Mumbai , , , , Maharashtra					
AMC Details :					
Expiry Date :	01-01-1970 05:30:00		Type :		
Product Name :	cCTV-Intercom				
Complain :	A Wing TV off issue A wing and B wing lift lobby intercom issue - With 2 phone need to send				
Technician Comment :	A wing tv issue resolved boath wing working ok and lobby intercom boath wing new cabling required approx 50 metr				
Complain Operator :	Desktop - Apurva Vajaria				
Remark :	A wing tv issue resolved boath wing working ok and lobby intercom boath wing new cabling required approx 50 metr				
Status History :	Date Time	Technician Name	Status	Remark	Sign
	14-08-2025 11:55:18	Atique Salmani	Awaiting Spares	A wing tv issue resolved boath wing working ok and lobby intercom boath wing new cabling required approx 50 metr	
	14-08-2025 11:55:18	Atique Salmani	Awaiting Spares	A wing tv issue resolved boath wing working ok and lobby intercom boath wing new cabling required approx 50 metr	
	14-08-2025 11:52:48	Atique Salmani	New		-

Previous Complain History :			
	Date Time	Technician Name	Remark
	06-09-2025 11:55:22	Atique Salmani	A wing extender installation done working ok boath wing
	05-09-2025 01:45:07	Ravi Rajbhar	Eden garden A wing lobby extension no.100 ok working 1st lift Extension no. 101 ok working 2nd lift Extension no. 102 ok working B wing B wing lobby extension no. 200 line ok working but instument kepaid issue 1st lift Extension no. 201 ok working 2nd lift Extension no. 202 OK working And society office line ok working but instument issue bcz instument in side water ????