Vallabh Enterprises

 $\label{eq:Regd.office:401,shanti kutir,shivaji road,near thakur international school,kandivali(west) mumbai - 400067 \\ \text{Support:} \mid \textbf{W}: www.vallabhenterprises.com \\ \textbf{E}: vallabhsecure@yahoo.co.in \\ \end{cases}$

Service Status Details : VE15759								
Low								
Admin - Apurva Vajaria								
9869439970								
Atique Salmani		Technician Mobile :	8080922984					
Complain	Date & Time:	09-09-2025 05:04:43						
Vendor Details :								
Eden Garden	Customer's Mobile :	9869439970	Name:	Rajesh Sir				
Address:								
Mumbai , , , , Maharashtra								
AMC Details :								
01-01-1970 05:30:00		Type:						
cCTV-Intercom								
cameras flickering issue Society office intercom need to check again								
1.4 splitter changed and boath wing working ok and office monitor issue disconnect all input of cctv after that not working monitor so issue in monitor .								
Desktop - Apurva Vajaria								
1.4 splitter changed and boath wing working ok and office monitor issue disconnect all input of cctv after that not working monitor so issue in monitor .								
	Admin - Apurva Vaj 9869439970 Atique Salmani Complain Eden Garden arashtra 01-01-1970 05:30: cCTV-Intercom cameras flickering 1.4 splitter change cctv after that not value of the splitter change ctv after that not value of the splitter change cctv after that not value of the splitter change	Admin - Apurva Vajaria 9869439970 Atique Salmani Complain Date & Time: Eden Garden Customer's Mobile: narashtra 01-01-1970 05:30:00 cCTV-Intercom cameras flickering issue Society office in 1.4 splitter changed and boath wing work cut after that not working monitor so iss Desktop - Apurva Vajaria 1.4 splitter changed and boath wing work control of the	Admin - Apurva Vajaria 9869439970 Atique Salmani Date & Time: 09-09-2025 05:04:43 Eden Garden Customer's Mobile: 9869439970 Type: cCTV-Intercom cameras flickering issue Society office intercom need to check ag 1.4 splitter changed and boath wing working ok and office monitor cut after that not working monitor so issue in monitor. Desktop - Apurva Vajaria 1.4 splitter changed and boath wing working ok and office monitor.	Admin - Apurva Vajaria 9869439970 Atique Salmani Date & Time: 09-09-2025 05:04:43 Eden Garden Customer's Mobile: 9869439970 Name: narashtra 01-01-1970 05:30:00 Type: cCTV-Intercom cameras flickering issue Society office intercom need to check again 1.4 splitter changed and boath wing working ok and office monitor issue disconn cctv after that not working monitor so issue in monitor. Desktop - Apurva Vajaria 1.4 splitter changed and boath wing working ok and office monitor issue disconn				

Status History :	Date Time	Technician Name	Status	Remark	Sign
	12-09-2025 11:00:11	Atique Salmani	Completed	1.4 splitter changed and boath wing working ok and office monitor issue disconnect all input of cctv after that not working monitor so issue in monitor.	onton
	12-09-2025 11:00:11	Atique Salmani	Completed	1.4 splitter changed and boath wing working ok and office monitor issue disconnect all input of cctv after that not working monitor so issue in monitor.	altan
	12-09-2025 10:44:12	Atique Salmani	New		-
	10-09-2025 07:05:51	Atique Salmani	Work Pending	1 x 4 hdmi spliter Nee tu change and check	(malu)
	10-09-2025 05:45:30	Atique Salmani	New		-
	09-09-2025 05:04:57	Atique Salmani	New		-
Previous Complain History :	Date Time	Technician Name	Remark		
	19-11-2025 01:33:04	Neeraj Chauhan	Hard disk installation done work okk 2 nos folty camera return		
	15-11-2025 11:51:45	Neeraj Chauhan	a wing 401 issue solved and security cabine phone not working		