




# Vallabh Enterprises

**Regd. Office :** 401,shanti kutir,shivaji road,near thakur international school,kandivali(west) mumbai - 400067  
**Support :** | **W :** www.vallabhenterprises.com  
**E :** vallabhsecure@yahoo.co.in

<b>Service Status Details : VE3367</b>					
<b>Priority :</b>	Low				
<b>Created By :</b>	Admin - Apurva Vajaria				
<b>Complaint Mob. No. :</b>	9869439970				
<b>Technician Name :</b>	Ravi Rajbhar		<b>Technician Mobile :</b>	8080922965	
<b>Ticket Type :</b>	Call Basis	<b>Date &amp; Time :</b>	05-07-2021 11:07:33		
<b>Vendor Details :</b>					
Company Name/Client Name :	Eden Garden	Customer's Mobile :	9869439970	Name :	Rajesh Sir
<b>Address :</b>					
Mumbai , , , , Maharashtra					
<b>AMC Details :</b>					
Expiry Date :	01-01-1970 05:30:00		Type :		
<b>Product Name :</b>	CCTV				
<b>Complain :</b>	dressing of cctv and intercom				
<b>Technician Comment :</b>	intercom system a wing and b wing cable dressing done both side and b wing lobby camera angle set and b wing 30 pair juction box install Mattel				
<b>Complain Operator :</b>	Desktop - Apurva Vajaria				
<b>Remark :</b>	intercom system a wing and b wing cable dressing done both side and b wing lobby camera angle set and b wing 30 pair juction box install Mattel				

<b>Status History :</b>	Date Time	Technician Name	Status	Remark	Sign
	07-07-2021 07:04:22	Ravi Rajbhar	Completed	intercom system a wing and b wing cable dressing done both side and b wing lobby camera angle set and b wing 30 pair junction box install Mattel	
	06-07-2021 07:16:01	Ravi Rajbhar	In Progress	intercom a wing Cron dressing done and b wing pending a wing 802 cable issue 401/402 line ok instrument issue	
	06-07-2021 10:00:56	Ravi Rajbhar	New		-
	05-07-2021 08:17:23	Ravi Rajbhar	Work Pending	dvr side dressing done and out side camera side cable shift and b wing back side pipe cables sift to wall and all camera working ok 2) A wing some flats intercom lines check and working ok 3) B wing intercom check pending	
	05-07-2021 11:07:45	Ravi Rajbhar	New		-
	05-07-2021 11:07:33	Ravi Rajbhar	New		-
<b>Previous Complain History :</b>	Date Time	Technician Name	Remark		
	05-08-2023 10:43:03	Atique Salmani	Intercom b 901 not using A 902 was disconnected intercom so check and reconnection from board working ok and lobby b wing camera 2 cable faulty not getting continuity so use another pair and working ok.		
	02-08-2023 03:34:48	Ishwar Meena	Camera no. 16 and 19 flickering issue resolved		