

Vallabh Enterprises

Regd. Office : 401,shanti kutir,shivaji road,near thakur international school,kandivali(west) mumbai - 400067
Support : | W : www.vallabhenterprises.com
E : vallabhsecure@yahoo.co.in

Service Status Details : VE3516																																			
Priority :	Low																																		
Created By :	Admin - Apurva Vajaria																																		
Complaint Mob. No. :	9869439970																																		
Technician Name :	Atique Salmani		Technician Mobile :	8080922984																															
Ticket Type :	Complain	Date & Time :	29-07-2021 11:09:46																																
Vendor Details :																																			
Company Name/Client Name :	Eden Garden	Customer's Mobile :	9869439970	Name :	Rajesh Sir																														
Address :																																			
Mumbai , , , , Maharashtra																																			
AMC Details :																																			
Expiry Date :	01-01-1970 05:30:00		Type :																																
Product Name :	Intercom																																		
Complain :	security cabin phone not working chairman flat b - 502 line not working																																		
Technician Comment :	901 new phone installled working ok 301 working ok 401 phone issue 402:ok 201 l ock 501 again lock.																																		
Complain Operator :	Desktop - Apurva Vajaria																																		
Remark :	901 new phone installled working ok 301 working ok 401 phone issue 402:ok 201 l ock 501 again lock.																																		
Status History :	<table><thead><tr><th>Date Time</th><th>Technician Name</th><th>Status</th><th>Remark</th><th>Sign</th></tr></thead><tbody><tr><td>07-08-2021 01:02:51</td><td>Atique Salmani</td><td>Completed</td><td>901 new phone installled working ok 301 working ok 401 phone issue 402:ok 201 l ock 501 again lock.</td><td></td></tr><tr><td>07-08-2021 10:29:54</td><td>Atique Salmani</td><td>New</td><td></td><td>-</td></tr><tr><td>29-07-2021 01:27:49</td><td>Atique Salmani</td><td>Work Pending</td><td>security cabin cable issue need to change(70-80 meter) b 302 issue resolved b 502 chairman also ok working a wing 401 /402 not check bcz client not approve in home</td><td></td></tr><tr><td>29-07-2021 11:10:01</td><td>Atique Salmani</td><td>New</td><td></td><td>-</td></tr><tr><td>29-07-2021 11:09:46</td><td>Atique Salmani</td><td>New</td><td></td><td>-</td></tr></tbody></table>					Date Time	Technician Name	Status	Remark	Sign	07-08-2021 01:02:51	Atique Salmani	Completed	901 new phone installled working ok 301 working ok 401 phone issue 402:ok 201 l ock 501 again lock.		07-08-2021 10:29:54	Atique Salmani	New		-	29-07-2021 01:27:49	Atique Salmani	Work Pending	security cabin cable issue need to change(70-80 meter) b 302 issue resolved b 502 chairman also ok working a wing 401 /402 not check bcz client not approve in home		29-07-2021 11:10:01	Atique Salmani	New		-	29-07-2021 11:09:46	Atique Salmani	New		-
Date Time	Technician Name	Status	Remark	Sign																															
07-08-2021 01:02:51	Atique Salmani	Completed	901 new phone installled working ok 301 working ok 401 phone issue 402:ok 201 l ock 501 again lock.																																
07-08-2021 10:29:54	Atique Salmani	New		-																															
29-07-2021 01:27:49	Atique Salmani	Work Pending	security cabin cable issue need to change(70-80 meter) b 302 issue resolved b 502 chairman also ok working a wing 401 /402 not check bcz client not approve in home																																
29-07-2021 11:10:01	Atique Salmani	New		-																															
29-07-2021 11:09:46	Atique Salmani	New		-																															

Previous Complain History :			
	Date Time	Technician Name	Remark
	05-08-2023 10:43:03	Atique Salmani	Intercom b 901 not using A 902 was disconnected intercom so check and reconnection from board working ok and lobby b wing camera 2 cable faulty not getting continuity so use another pair and working ok.
	02-08-2023 03:34:48	Ishwar Meena	Camera no. 16 and 19 flickering issue resolved