## Vallabh Enterprises

 $\label{eq:Regd.office:401,shanti kutir,shivaji road,near thakur international school,kandivali(west) mumbai - 400067 \\ \text{Support:} \mid \textbf{W}: www.vallabhenterprises.com \\ \textbf{E}: vallabhsecure@yahoo.co.in \\ \end{cases}$ 

Service Status Details : VE4437								
Priority:	Low							
Created By:	Admin - Apurva Vajaria							
Complaint Mob. No. :	9869439970							
Technician Name :	Yogesh Desai		Technician Mobile :	8080922963				
Ticket Type :	Complain	Date & Time :	22-12-2021 10:46:47					
Vendor Details :								
Company Name/Client Name :	Eden Garden	Customer's Mobile :	9869439970	Name :	Rajesh Sir			
Address:								
Mumbai , , , , Maharashtra								
AMC Details :								
Expiry Date :	01-01-1970 05:30:00		Type:					
<b>Product Name:</b>	Intercom							
Complain:	B-1101 & B-1202 intercom issue							
Technician Comment :	B wing 1101 intercom cable was cut in the duct cable joined again intercom working ok. flat no 1202 client not available. CCTV hard disk was not detecting . after restarting the dvr hard disk become normal all working ok. hard disk need to be kept under observation.							
Complain Operator :	Desktop - Apurva Vajaria							
Remark:	B wing 1101 intercom cable was cut in the duct cable joined again intercom working ok. flat no 1202 client not available. CCTV hard disk was not detecting . after restarting the dvr hard disk become normal all working ok. hard disk need to be kept under observation.							

<b>Status History:</b>	Date Time	Technician Name	Status	Remark	Sign	
	29-01-2022 06:37:43	YogeshDesai	Completed	B wing 1101 intercom cable was cut in the duct cable joined again intercom working ok. flat no 1202 client not available. CCTV hard disk was not detecting . after restarting the dvr hard disk become normal all working ok. hard disk need to be kept under observation.		
	29-01-2022 06:28:18	YogeshDesai	New		-	
	29-01-2022 05:47:38	YogeshDesai	New		-	
	22-12-2021 01:00:31	YogeshDesai	Client Side	cable cut by electrician flate nmbr 1101 1201 .1202 1202 cable check and find out and rejoint working ok but 2 flate cable missing need to find out by electrician .		
	22-12-2021 10:47:13	YogeshDesai	New		-	
	22-12-2021 10:46:47	YogeshDesai	New		-	
Previous	Date Time	Technician Name		Remark		
Complain History :	10-02-2022 10:36:24	Siddhesh Chavan		intercom system off and on issue resolved and system under observation		
29-01-2022 05:48:00 ChandanYadav dvr on off essu Change the d				ssu Change the dvr adapter .		