




# Vallabh Enterprises

Regd. Office : 401,shanti kutir,shivaji road,near thakur international school,kandivali(west) mumbai - 400067  
Support : | W : www.vallabhenterprises.com  
E : vallabhsecure@yahoo.co.in

<b>Service Status Details : VE6155</b>																									
<b>Priority :</b>	Low																								
<b>Created By :</b>	Admin - Apurva Vajaria																								
<b>Complaint Mob. No. :</b>	9869439970																								
<b>Technician Name :</b>	Siddhesh Chavan		<b>Technician Mobile :</b>	8080922985																					
<b>Ticket Type :</b>	Complain	<b>Date &amp; Time :</b>	09-08-2022 09:58:33																						
<b>Vendor Details :</b>																									
Company Name/Client Name :	Eden Garden	Customer's Mobile :	9869439970	Name :	Rajesh Sir																				
<b>Address :</b>																									
Mumbai , , , , Maharashtra																									
<b>AMC Details :</b>																									
Expiry Date :	01-01-1970 05:30:00		Type :																						
<b>Product Name :</b>	cCTV-Intercom																								
<b>Complain :</b>	lift -2 and flat no 3 intercom not working and Disturbance issue in tv viewing																								
<b>Technician Comment :</b>	a wing 301 intercom issue resolved cable rejoined and b wing 1 st lift phone issue and 3 no camera side not connector cable joint																								
<b>Complain Operator :</b>	Desktop - Apurva Vajaria																								
<b>Remark :</b>	a wing 301 intercom issue resolved cable rejoined and b wing 1 st lift phone issue and 3 no camera side not connector cable joint																								
<b>Status History :</b>	<table><thead><tr><th>Date Time</th><th>Technician Name</th><th>Status</th><th>Remark</th><th>Sign</th></tr></thead><tbody><tr><td>09-08-2022 11:35:48</td><td>Siddhesh Chavan</td><td>Completed</td><td>a wing 301 intercom issue resolved cable rejoined and b wing 1 st lift phone issue and 3 no camera side not connector cable joint</td><td></td></tr><tr><td>09-08-2022 09:58:50</td><td>Siddhesh Chavan</td><td>New</td><td></td><td>-</td></tr><tr><td>09-08-2022 09:58:33</td><td>Siddhesh Chavan</td><td>New</td><td></td><td>-</td></tr></tbody></table>					Date Time	Technician Name	Status	Remark	Sign	09-08-2022 11:35:48	Siddhesh Chavan	Completed	a wing 301 intercom issue resolved cable rejoined and b wing 1 st lift phone issue and 3 no camera side not connector cable joint		09-08-2022 09:58:50	Siddhesh Chavan	New		-	09-08-2022 09:58:33	Siddhesh Chavan	New		-
Date Time	Technician Name	Status	Remark	Sign																					
09-08-2022 11:35:48	Siddhesh Chavan	Completed	a wing 301 intercom issue resolved cable rejoined and b wing 1 st lift phone issue and 3 no camera side not connector cable joint																						
09-08-2022 09:58:50	Siddhesh Chavan	New		-																					
09-08-2022 09:58:33	Siddhesh Chavan	New		-																					
<b>Previous Complain History :</b>	<table><thead><tr><th>Date Time</th><th>Technician Name</th><th>Remark</th></tr></thead><tbody><tr><td>06-08-2022 10:15:09</td><td>Siddhesh Chavan</td><td>4 lift camera check and ok working but camera disturbances issue also bcz cable joint check recoding</td></tr><tr><td>04-08-2022 10:39:06</td><td>Atique Salmani</td><td>ppm done all working ok only 19 nmbr being lift camera black n white when show flash light it's color soncamera sensor weak need to change.</td></tr></tbody></table>					Date Time	Technician Name	Remark	06-08-2022 10:15:09	Siddhesh Chavan	4 lift camera check and ok working but camera disturbances issue also bcz cable joint check recoding	04-08-2022 10:39:06	Atique Salmani	ppm done all working ok only 19 nmbr being lift camera black n white when show flash light it's color soncamera sensor weak need to change.											
Date Time	Technician Name	Remark																							
06-08-2022 10:15:09	Siddhesh Chavan	4 lift camera check and ok working but camera disturbances issue also bcz cable joint check recoding																							
04-08-2022 10:39:06	Atique Salmani	ppm done all working ok only 19 nmbr being lift camera black n white when show flash light it's color soncamera sensor weak need to change.																							