




Vallabh Enterprises

Regd. Office : 401,shanti kutir,shivaji road,near thakur international school,kandivali(west) mumbai - 400067
Support : | W : www.vallabhenterprises.com
E : vallabhsecure@yahoo.co.in

Service Status Details : VE6385																									
Priority :	Low																								
Created By :	Admin - Apurva Vajaria																								
Complaint Mob. No. :	9869439970																								
Technician Name :	Siddhesh Chavan		Technician Mobile :	8080922985																					
Ticket Type :	Complain	Date & Time :	16-09-2022 10:40:34																						
Vendor Details :																									
Company Name/Client Name :	Eden Garden	Customer's Mobile :	9869439970	Name :	Rajesh Sir																				
Address :																									
Mumbai , , , , Maharashtra																									
AMC Details :																									
Expiry Date :	01-01-1970 05:30:00		Type :																						
Product Name :	CCTV																								
Complain :	A-302 intercom line issue need to check + office intercom not working + encode resolution changed frequently appears on screen																								
Technician Comment :	a wing 302 line working ok and dvr tv view working ok and a wing lift camera side flat cable and dvr side rj 6 cable and b wing 2 nd lift camera side rj 6 and office phone issue need to change																								
Complain Operator :	Desktop - Apurva Vajaria																								
Remark :	a wing 302 line working ok and dvr tv view working ok and a wing lift camera side flat cable and dvr side rj 6 cable and b wing 2 nd lift camera side rj 6 and office phone issue need to change																								
Status History :	<table><thead><tr><th>Date Time</th><th>Technician Name</th><th>Status</th><th>Remark</th><th>Sign</th></tr></thead><tbody><tr><td>16-09-2022 02:59:08</td><td>Siddhesh Chavan</td><td>Completed</td><td>a wing 302 line working ok and dvr tv view working ok and a wing lift camera side flat cable and dvr side rj 6 cable and b wing 2 nd lift camera side rj 6 and office phone issue need to change</td><td></td></tr><tr><td>16-09-2022 10:40:48</td><td>Siddhesh Chavan</td><td>New</td><td></td><td>-</td></tr><tr><td>16-09-2022 10:40:34</td><td>Siddhesh Chavan</td><td>New</td><td></td><td>-</td></tr></tbody></table>					Date Time	Technician Name	Status	Remark	Sign	16-09-2022 02:59:08	Siddhesh Chavan	Completed	a wing 302 line working ok and dvr tv view working ok and a wing lift camera side flat cable and dvr side rj 6 cable and b wing 2 nd lift camera side rj 6 and office phone issue need to change		16-09-2022 10:40:48	Siddhesh Chavan	New		-	16-09-2022 10:40:34	Siddhesh Chavan	New		-
Date Time	Technician Name	Status	Remark	Sign																					
16-09-2022 02:59:08	Siddhesh Chavan	Completed	a wing 302 line working ok and dvr tv view working ok and a wing lift camera side flat cable and dvr side rj 6 cable and b wing 2 nd lift camera side rj 6 and office phone issue need to change																						
16-09-2022 10:40:48	Siddhesh Chavan	New		-																					
16-09-2022 10:40:34	Siddhesh Chavan	New		-																					
Previous Complain History :	<table><thead><tr><th>Date Time</th><th>Technician Name</th><th>Remark</th></tr></thead><tbody><tr><td>16-09-2022 05:12:06</td><td>Siddhesh Chavan</td><td>b wing 602 line ok phone problem 1201 line ok phone ok switch board intrcome line Port issue need to change</td></tr><tr><td>10-09-2022 11:20:04</td><td>YogeshDesai</td><td>camera no 16 of a wing lift camera is now ok camera reconnect and working ok camera to be kept under observation.</td></tr></tbody></table>					Date Time	Technician Name	Remark	16-09-2022 05:12:06	Siddhesh Chavan	b wing 602 line ok phone problem 1201 line ok phone ok switch board intrcome line Port issue need to change	10-09-2022 11:20:04	YogeshDesai	camera no 16 of a wing lift camera is now ok camera reconnect and working ok camera to be kept under observation.											
Date Time	Technician Name	Remark																							
16-09-2022 05:12:06	Siddhesh Chavan	b wing 602 line ok phone problem 1201 line ok phone ok switch board intrcome line Port issue need to change																							
10-09-2022 11:20:04	YogeshDesai	camera no 16 of a wing lift camera is now ok camera reconnect and working ok camera to be kept under observation.																							