Vallabh Enterprises

 $\label{eq:Regd.office:401,shanti kutir,shivaji road,near thakur international school,kandivali(west) mumbai - 400067 \\ \text{Support:} \mid \textbf{W}: www.vallabhenterprises.com \\ \textbf{E}: vallabhsecure@yahoo.co.in \\ \end{cases}$

Service Status De	tails: VE6453						
Priority:	Low						
Created By:	Admin - Apurva Vajaria						
Complaint Mob.	9869439970						
Technician Name :	Siddhesh Chavan		Technician Mobile: 808		8080922985	080922985	
Ticket Type :	Complain	Date & Time :	27-09-2022 11:17:50				
Vendor Details :			•				
Company Name/Client Name :	Eden Garden	Customer's Mobile :	9869439970		Name :	Rajesh Sir	
Address :			•				
Mumbai , , , , Ma	harashtra						
AMC Details :							
Expiry Date :	01-01-1970 05:30:	Type:					
Product Name:	CCTV						
Complain :	b wing camera no. 18 lift camera off issue + survey for how many cameras working on joints.						
Technician Comment :	b wing 18 no lift camera power adapter issue and install new power supply and camera working ok						
Complain Operator :	Desktop - Apurva Vajaria						
Remark:	b wing 18 no lift camera power adapter issue and install new power supply and camera working ok						
Status History:	Date Time	Technician Name	Status		Remark	Sign	
	30-09-2022 12:04:57	7 Siddhesh Chavan	Completed	power install	18 no lift camera adapter issue and new power supply mera working ok	[] X 2	
	30-09-2022 10:24:59	Siddhesh Chavan	New			-	
	27-09-2022 02:26:49	Siddhesh Chavan	Work Pending	issue a	lift camera power nd work pending son required for ng	/r\\\	
	27-09-2022 11:18:24		New			-	
	27-09-2022 11:17:50	Siddhesh Chavan	New			-	

Previous Complain History :	Date Time	Technician Name	Remark		
	16-09-2022 05:12:06	Siddhesh Chavan	b wing 602 line ok phone problem 1201 line ok phone ok switch board intrcome line Port issue need to change		
	16-09-2022 10:40:34	Siddhesh Chavan	a wing 302 line working ok and dvr tv view working ok and a wing lift camera side flat cable and dvr side rj 6 cable and b wing 2 nd lift camera side rj 6 and office phone issue need to change		