




# Vallabh Enterprises

Regd. Office : 401,shanti kutir,shivaji road,near thakur international school,kandivali(west) mumbai - 400067  
Support : | W : www.vallabhenterprises.com  
E : vallabhsecure@yahoo.co.in

<b>Service Status Details : VE7576</b>																				
<b>Priority :</b>	Low																			
<b>Created By :</b>	Admin - Apurva Vajaria																			
<b>Complaint Mob. No. :</b>	9869439970																			
<b>Technician Name :</b>	Atique Salmani		<b>Technician Mobile :</b>	8080922984																
<b>Ticket Type :</b>	Complain	<b>Date &amp; Time :</b>	08-02-2023 02:40:04																	
<b>Vendor Details :</b>																				
Company Name/Client Name :	Eden Garden	Customer's Mobile :	9869439970	Name :	Rajesh Sir															
<b>Address :</b>																				
Mumbai , , , , Maharashtra																				
<b>AMC Details :</b>																				
Expiry Date :	01-01-1970 05:30:00		Type :																	
<b>Product Name :</b>	Intercom																			
<b>Complain :</b>	intercom system not working																			
<b>Technician Comment :</b>	B wing 792 cable need to lay 702 duct to 2 floor duct And lobby cable Jack faulty so direct connection done working ok. And awing 202 working ok only visit .all working ok.																			
<b>Complain Operator :</b>	Desktop - Apurva Vajaria																			
<b>Remark :</b>	B wing 792 cable need to lay 702 duct to 2 floor duct And lobby cable Jack faulty so direct connection done working ok. And awing 202 working ok only visit .all working ok.																			
<b>Status History :</b>	<table><thead><tr><th>Date Time</th><th>Technician Name</th><th>Status</th><th>Remark</th><th>Sign</th></tr></thead><tbody><tr><td>08-02-2023 05:00:10</td><td>Atique Salmani</td><td>Completed</td><td>B wing 792 cable need to lay 702 duct to 2 floor duct And lobby cable Jack faulty so direct connection done working ok. And awing 202 working ok only visit .all working ok.</td><td></td></tr><tr><td>08-02-2023 02:40:12</td><td>Atique Salmani</td><td>New</td><td></td><td>-</td></tr></tbody></table>					Date Time	Technician Name	Status	Remark	Sign	08-02-2023 05:00:10	Atique Salmani	Completed	B wing 792 cable need to lay 702 duct to 2 floor duct And lobby cable Jack faulty so direct connection done working ok. And awing 202 working ok only visit .all working ok.		08-02-2023 02:40:12	Atique Salmani	New		-
Date Time	Technician Name	Status	Remark	Sign																
08-02-2023 05:00:10	Atique Salmani	Completed	B wing 792 cable need to lay 702 duct to 2 floor duct And lobby cable Jack faulty so direct connection done working ok. And awing 202 working ok only visit .all working ok.																	
08-02-2023 02:40:12	Atique Salmani	New		-																
<b>Previous Complain History :</b>	<table><thead><tr><th>Date Time</th><th>Technician Name</th><th>Remark</th></tr></thead><tbody><tr><td>09-02-2023 11:19:28</td><td>Ravi Rajbhar</td><td>Cctv camera check 19 number camera check and reconnection b wing second lift camera And a wing 802 need to change cable flat to 2nd floor junction box A wing 1102 intercom issue resolved check cable flat to duct duct to 2nd floor junction box then connect cable and ok working done B wing 1102 intercom issue resolved B wing 201 cable check duct to flat then cable connected in system then ok working done B wing 1201 cable check duct to flat then connect cable junction box line ok but no instrument</td></tr><tr><td>31-01-2023 10:44:04</td><td>Sonu Kumar</td><td>Camera no 4 off issue resolved working ok</td></tr></tbody></table>					Date Time	Technician Name	Remark	09-02-2023 11:19:28	Ravi Rajbhar	Cctv camera check 19 number camera check and reconnection b wing second lift camera And a wing 802 need to change cable flat to 2nd floor junction box A wing 1102 intercom issue resolved check cable flat to duct duct to 2nd floor junction box then connect cable and ok working done B wing 1102 intercom issue resolved B wing 201 cable check duct to flat then cable connected in system then ok working done B wing 1201 cable check duct to flat then connect cable junction box line ok but no instrument	31-01-2023 10:44:04	Sonu Kumar	Camera no 4 off issue resolved working ok						
Date Time	Technician Name	Remark																		
09-02-2023 11:19:28	Ravi Rajbhar	Cctv camera check 19 number camera check and reconnection b wing second lift camera And a wing 802 need to change cable flat to 2nd floor junction box A wing 1102 intercom issue resolved check cable flat to duct duct to 2nd floor junction box then connect cable and ok working done B wing 1102 intercom issue resolved B wing 201 cable check duct to flat then cable connected in system then ok working done B wing 1201 cable check duct to flat then connect cable junction box line ok but no instrument																		
31-01-2023 10:44:04	Sonu Kumar	Camera no 4 off issue resolved working ok																		