


Vallabh Enterprises

Regd. Office : 401,shanti kutir,shivaji road,near thakur international school,kandivali(west) mumbai - 400067
Support : | W : www.vallabhenterprises.com
E : vallabhsecure@yahoo.co.in

Service Status Details : VE7589					
Priority :	Low				
Created By :	Admin - Apurva Vajaria				
Complaint Mob. No. :	9869439970				
Technician Name :	Ravi Rajbhar		Technician Mobile :	8080922965	
Ticket Type :	Complain	Date & Time :	09-02-2023 11:19:28		
Vendor Details :					
Company Name/Client Name :	Eden Garden	Customer's Mobile :	9869439970	Name :	Rajesh Sir
Address :					
Mumbai , , , , Maharashtra					
AMC Details :					
Expiry Date :	01-01-1970 05:30:00		Type :		
Product Name :	cCTV-Intercom				
Complain :	A wing 1102/A wing 802/B wing 1102/b wing 201/b wing 1201 intercom issue and camera no. 19 need to check				
Technician Comment :	Cctv camera check 19 number camera check and reconnection b wing second lift camera And a wing 802 need to change cable flat to 2nd floor junction box A wing 1102 intercom issue resolved check cable flat to duct duct to 2nd floor junction box then connect cable and ok working done B wing 1102 intercom issue resolved B wing 201 cable check duct to flat then cable connected in system then ok working done B wing 1201 cable check duct to flat then connect cable junction box line ok but no instrument				
Complain Operator :	Desktop - Apurva Vajaria				
Remark :	Cctv camera check 19 number camera check and reconnection b wing second lift camera And a wing 802 need to change cable flat to 2nd floor junction box A wing 1102 intercom issue resolved check cable flat to duct duct to 2nd floor junction box then connect cable and ok working done B wing 1102 intercom issue resolved B wing 201 cable check duct to flat then cable connected in system then ok working done B wing 1201 cable check duct to flat then connect cable junction box line ok but no instrument				

Status History :					
	Date Time	Technician Name	Status	Remark	Sign
	09-02-2023 02:35:26	Ravi Rajbhar	Completed	Cctv camera check 19 number camera check and reconnection b wing second lift camera And a wing 802 need to change cable flat to 2nd floor junction box A wing 1102 intercom issue resolved check cable flat to duct duct to 2nd floor junction box then connect cable and ok working done B wing 1102 intercom issue resolved B wing 201 cable check duct to flat then cable connected in system then ok working done B wing 1201 cable check duct to flat then connect cable junction box line ok but no instrument	
	09-02-2023 11:19:49	Ravi Rajbhar	New		-
Previous Complain History :					
	Date Time	Technician Name	Remark		
	08-02-2023 02:40:04	Atique Salmani	B wing 792 cable need to lay 702 duct to 2 floor duct And lobby cable Jack faulty so direct connection done working ok. And awing 202 working ok only visit .all working ok.		
	31-01-2023 10:44:04	Sonu Kumar	Camera no 4 off issue resolved working ok		