




Vallabh Enterprises

Regd. Office : 401,shanti kutir,shivaji road,near thakur international school,kandivali(west) mumbai - 400067
Support : | W : www.vallabhenterprises.com
E : vallabhsecure@yahoo.co.in

Service Status Details : VE7652																				
Priority :	Low																			
Created By :	Admin - Apurva Vajaria																			
Complaint Mob. No. :	9869439970																			
Technician Name :	Sonu Kumar		Technician Mobile :	8454016444																
Ticket Type :	Complain	Date & Time :	17-02-2023 10:39:20																	
Vendor Details :																				
Company Name/Client Name :	Eden Garden	Customer's Mobile :	9869439970	Name :	Rajesh Sir															
Address :																				
Mumbai , , , , Maharashtra																				
AMC Details :																				
Expiry Date :	01-01-1970 05:30:00		Type :																	
Product Name :	CCTV																			
Complain :	b wing lift camera on off issue																			
Technician Comment :	B wing lift camera no 19 on off issue resolved working ok																			
Complain Operator :	Desktop - Apurva Vajaria																			
Remark :	B wing lift camera no 19 on off issue resolved working ok																			
Status History :	<table><thead><tr><th>Date Time</th><th>Technician Name</th><th>Status</th><th>Remark</th><th>Sign</th></tr></thead><tbody><tr><td>17-02-2023 11:48:13</td><td>Sonu Kumar</td><td>Completed</td><td>B wing lift camera no 19 on off issue resolved working ok</td><td></td></tr><tr><td>17-02-2023 10:39:28</td><td>Sonu Kumar</td><td>New</td><td></td><td>-</td></tr></tbody></table>					Date Time	Technician Name	Status	Remark	Sign	17-02-2023 11:48:13	Sonu Kumar	Completed	B wing lift camera no 19 on off issue resolved working ok		17-02-2023 10:39:28	Sonu Kumar	New		-
Date Time	Technician Name	Status	Remark	Sign																
17-02-2023 11:48:13	Sonu Kumar	Completed	B wing lift camera no 19 on off issue resolved working ok																	
17-02-2023 10:39:28	Sonu Kumar	New		-																
Previous Complain History :	<table><thead><tr><th>Date Time</th><th>Technician Name</th><th>Remark</th></tr></thead><tbody><tr><td>13-02-2023 10:04:46</td><td>Ravi Rajbhar</td><td>B wing 602 line ok instrument issue inform to client and security</td></tr><tr><td>09-02-2023 11:19:28</td><td>Ravi Rajbhar</td><td>Cctv camera check 19 number camera check and reconnection b wing second lift camera And a wing 802 need to change cable flat to 2nd floor junction box A wing 1102 intercom issue resolved check cable flat to duct duct to 2nd floor junction box then connect cable and ok working done B wing 1102 intercom issue resolved B wing 201 cable check duct to flat then cable connected in system then ok working done B wing 1201 cable check duct to flat then connect cable junction box line ok but no instrument</td></tr></tbody></table>					Date Time	Technician Name	Remark	13-02-2023 10:04:46	Ravi Rajbhar	B wing 602 line ok instrument issue inform to client and security	09-02-2023 11:19:28	Ravi Rajbhar	Cctv camera check 19 number camera check and reconnection b wing second lift camera And a wing 802 need to change cable flat to 2nd floor junction box A wing 1102 intercom issue resolved check cable flat to duct duct to 2nd floor junction box then connect cable and ok working done B wing 1102 intercom issue resolved B wing 201 cable check duct to flat then cable connected in system then ok working done B wing 1201 cable check duct to flat then connect cable junction box line ok but no instrument						
Date Time	Technician Name	Remark																		
13-02-2023 10:04:46	Ravi Rajbhar	B wing 602 line ok instrument issue inform to client and security																		
09-02-2023 11:19:28	Ravi Rajbhar	Cctv camera check 19 number camera check and reconnection b wing second lift camera And a wing 802 need to change cable flat to 2nd floor junction box A wing 1102 intercom issue resolved check cable flat to duct duct to 2nd floor junction box then connect cable and ok working done B wing 1102 intercom issue resolved B wing 201 cable check duct to flat then cable connected in system then ok working done B wing 1201 cable check duct to flat then connect cable junction box line ok but no instrument																		