

Vallabh Enterprises

Regd. Office : 401,shanti kutir,shivaji road,near thakur international school,kandivali(west) mumbai - 400067
Support : | W : www.vallabhenterprises.com
E : vallabhsecure@yahoo.co.in

Service Status Details : VE8676																				
Priority :	Low																			
Created By :	Admin - Apurva Vajaria																			
Complaint Mob. No. :	9820007487																			
Technician Name :	Kalpesh Subhash Gurav	Technician Mobile :	8879684054																	
Ticket Type :	Complain	Date & Time :	27-06-2023 10:12:07																	
Vendor Details :																				
Company Name/Client Name :	Shanti Apt	Customer's Mobile :	9820007487	Name :	Rajesh Sir															
Address :																				
Mumbai , , , Maharashtra																				
AMC Details :																				
Expiry Date :	01-01-1970 05:30:00		Type :																	
Product Name :	Intercom																			
Complain :	F wing 1103 Intercom issue																			
Technician Comment :	F Wing 1103 Not Using Intercom																			
Complain Operator :	Desktop - Apurva Vajaria																			
Remark :	F Wing 1103 Not Using Intercom																			
Status History :	<table><thead><tr><th>Date Time</th><th>Technician Name</th><th>Status</th><th>Remark</th><th>Sign</th></tr></thead><tbody><tr><td>27-06-2023 10:18:05</td><td>Kalpesh SubhashGurav</td><td>Completed</td><td>F Wing 1103 Not Using Intercom</td><td></td></tr><tr><td>27-06-2023 10:12:18</td><td>Kalpesh SubhashGurav</td><td>New</td><td></td><td>-</td></tr></tbody></table>					Date Time	Technician Name	Status	Remark	Sign	27-06-2023 10:18:05	Kalpesh SubhashGurav	Completed	F Wing 1103 Not Using Intercom		27-06-2023 10:12:18	Kalpesh SubhashGurav	New		-
Date Time	Technician Name	Status	Remark	Sign																
27-06-2023 10:18:05	Kalpesh SubhashGurav	Completed	F Wing 1103 Not Using Intercom																	
27-06-2023 10:12:18	Kalpesh SubhashGurav	New		-																
Previous Complain History :	<table><thead><tr><th>Date Time</th><th>Technician Name</th><th>Remark</th></tr></thead><tbody><tr><td>01-07-2023 04:47:27</td><td>Ishwar Meena</td><td>Out door SMPS faulty due to short circuit becuz 230 volt plug point in outdoor so insert water in 230 volt so it's become short circuit.</td></tr><tr><td>25-05-2023 10:40:03</td><td>Kalpesh SubhashGurav</td><td>F Wing TV Remote missing require remote to check the TV</td></tr></tbody></table>					Date Time	Technician Name	Remark	01-07-2023 04:47:27	Ishwar Meena	Out door SMPS faulty due to short circuit becuz 230 volt plug point in outdoor so insert water in 230 volt so it's become short circuit.	25-05-2023 10:40:03	Kalpesh SubhashGurav	F Wing TV Remote missing require remote to check the TV						
Date Time	Technician Name	Remark																		
01-07-2023 04:47:27	Ishwar Meena	Out door SMPS faulty due to short circuit becuz 230 volt plug point in outdoor so insert water in 230 volt so it's become short circuit.																		
25-05-2023 10:40:03	Kalpesh SubhashGurav	F Wing TV Remote missing require remote to check the TV																		