




# Vallabh Enterprises

**Regd. Office :** 401,shanti kutir,shivaji road,near thakur international school,kandivali(west) mumbai - 400067  
**Support : | W :** www.vallabhenterprises.com  
**E :** vallabhsecure@yahoo.co.in

<b>Service Status Details : VE8722</b>																									
<b>Priority :</b>	Low																								
<b>Created By :</b>	Admin - Apurva Vajaria																								
<b>Complaint Mob. No. :</b>	9820007487																								
<b>Technician Name :</b>	Ishwar Meena		<b>Technician Mobile :</b>	9165341500																					
<b>Ticket Type :</b>	Complain	<b>Date &amp; Time :</b>	01-07-2023 04:47:27																						
<b>Vendor Details :</b>																									
<b>Company Name/Client Name :</b>	Shanti Apt	<b>Customer's Mobile :</b>	9820007487	<b>Name :</b>	Rajesh Sir																				
<b>Address :</b>																									
Mumbai , , , , Maharashtra																									
<b>AMC Details :</b>																									
<b>Expiry Date :</b>	01-01-1970 05:30:00		<b>Type :</b>																						
<b>Product Name :</b>	CCTV																								
<b>Complain :</b>	F wing Due to short circuit 2 pin adapter issue																								
<b>Technician Comment :</b>	Out door SMPS faulty due to short circuit bec 230 volt plug point in outdoor so insert water in 230 volt so it's become short circuit.																								
<b>Complain Operator :</b>	Desktop - Apurva Vajaria																								
<b>Remark :</b>	Out door SMPS faulty due to short circuit bec 230 volt plug point in outdoor so insert water in 230 volt so it's become short circuit.																								
<b>Status History :</b>	<table><thead><tr><th>Date Time</th><th>Technician Name</th><th>Status</th><th>Remark</th><th>Sign</th></tr></thead><tbody><tr><td>05-07-2023 10:22:29</td><td>Ishwar Meena</td><td>New</td><td></td><td>-</td></tr><tr><td>01-07-2023 05:10:29</td><td>Ishwar Meena</td><td>Work Pending</td><td>Out door SMPS faulty due to short circuit bec 230 volt plug point in outdoor so insert water in 230 volt so it's become short circuit.</td><td></td></tr><tr><td>01-07-2023 04:47:43</td><td>Ishwar Meena</td><td>New</td><td></td><td>-</td></tr></tbody></table>					Date Time	Technician Name	Status	Remark	Sign	05-07-2023 10:22:29	Ishwar Meena	New		-	01-07-2023 05:10:29	Ishwar Meena	Work Pending	Out door SMPS faulty due to short circuit bec 230 volt plug point in outdoor so insert water in 230 volt so it's become short circuit.		01-07-2023 04:47:43	Ishwar Meena	New		-
Date Time	Technician Name	Status	Remark	Sign																					
05-07-2023 10:22:29	Ishwar Meena	New		-																					
01-07-2023 05:10:29	Ishwar Meena	Work Pending	Out door SMPS faulty due to short circuit bec 230 volt plug point in outdoor so insert water in 230 volt so it's become short circuit.																						
01-07-2023 04:47:43	Ishwar Meena	New		-																					
<b>Previous Complain History :</b>	<table><thead><tr><th>Date Time</th><th>Technician Name</th><th>Remark</th></tr></thead><tbody><tr><td>12-08-2023 11:08:15</td><td>InzmamUl Haq</td><td></td></tr><tr><td>25-07-2023 05:38:41</td><td>Ravi Rajbhar</td><td>securitey intercom issue relsolved and ok workong done</td></tr></tbody></table>					Date Time	Technician Name	Remark	12-08-2023 11:08:15	InzmamUl Haq		25-07-2023 05:38:41	Ravi Rajbhar	securitey intercom issue relsolved and ok workong done											
Date Time	Technician Name	Remark																							
12-08-2023 11:08:15	InzmamUl Haq																								
25-07-2023 05:38:41	Ravi Rajbhar	securitey intercom issue relsolved and ok workong done																							