Vallabh Enterprises

Regd. Office : 401, shanti kutir, shivaji road, near thakur international school, kandivali(west) mumbai - 400067 Support : | W : www.vallabhenterprises.com E : vallabhsecure@yahoo.co.in

Service Status Details : VE3663 Low **Priority** : **Created By :** Admin - Apurva Vajaria **Complaint Mob.** 9892073010 **No. : Technician** Ravi Rajbhar **Technician Mobile** 8080922965 Name : New Installation Date & Time : 19-08-2021 10:51:44 **Ticket Type : Vendor Details :** 9892073010 Company Damji Shamji -Customer's Mobile Name : Rajesh Name/Client Mahavir Estella Name : Address : Mumbai,,,, Maharashtra **AMC Details :** 01-01-1970 05:30:00 Expiry Date : Type : **Product Name :** CCTV **Complain**: need to do cabling of CCTV Cameras hdmi extender install both side and ok working done and TV viewing ok 1 metr cable return pull Technician DVR side and jouinder remove and return office **Comment** : Complain Desktop - Apurva Vajaria **Operator** : **Remark** : hdmi extender install both side and ok working done and TV viewing ok 1 metr cable return pull DVR side and jouinder remove and return office **Status History :** Technician Date Time Status Remark Sign Name 06-12-2021 Completed hdmi extender install both Ravi Rajbhar side and ok working done 06:26:52 and TV viewing ok 1 metr cable return pull DVR side and jouinder remove and return office 06-12-2021 Ravi Rajbhar New 03.20.39 19-08-2021 Ravi Rajbhar Work Pending 2 Billy camera cabling done 05:41:41 and old camera wire removing and TV out and usb extender and lift cabling pending and lift camera piping TV and wire piping 19-08-2021 Ravi Rajbhar New 10:52:06 19-08-2021 Ravi Rajbhar New 10:51:45

Previous Complain History :	Date Time	Technician Name	Remark
	13-10-2022 11:20:11		Dilshad - DVR side hdmi cable issue rj45 issue so installed new rj45 connector issue resolved time and date recording off so start the recording work completed
	08-07-2022 03:25:57	Shiva Meena	There is electrical cable some joint issue thats why tv getting on and off and 1 camera screw fallen down so camera got tilted.