




Vallabh Enterprises

Regd. Office : 401,shanti kutir,shivaji road,near thakur international school,kandivali(west) mumbai - 400067
Support : | W : www.vallabhenterprises.com
E : vallabhsecure@yahoo.co.in

Service Status Details : VE11336																				
Priority :	Low																			
Created By :	Admin - Apurva Vajaria																			
Complaint Mob. No. :	9892982500																			
Technician Name :	Ravi Rajbhar		Technician Mobile :	8080922965																
Ticket Type :	Complain	Date & Time :	08-04-2024 03:41:51																	
Vendor Details :																				
Company Name/Client Name :	Lifescapes Mirage	Customer's Mobile :	9892982500	Name :	Rakesh Sanghavi															
Address :																				
Mumbai , , , 400028 , Maharashtra																				
AMC Details :																				
Expiry Date :	01-01-1970 05:30:00		Type :																	
Product Name :	Intercom																			
Complain :	Society office intercom not working																			
Technician Comment :	society office intercom issue resolved and ok working done and flat no.702 intercom issue resolved and back side fist lift ex.no.change 75 and 901 intercom issue resolved need to change port no. 0113 old port faulty 0017																			
Complain Operator :	Desktop - Apurva Vajaria																			
Remark :	society office intercom issue resolved and ok working done and flat no.702 intercom issue resolved and back side fist lift ex.no.change 75 and 901 intercom issue resolved need to change port no. 0113 old port faulty 0017																			
Status History :	<table><thead><tr><th>Date Time</th><th>Technician Name</th><th>Status</th><th>Remark</th><th>Sign</th></tr></thead><tbody><tr><td>10-04-2024 06:05:40</td><td>Ravi Rajbhar</td><td>Completed</td><td>society office intercom issue resolved and ok working done and flat no.702 intercom issue resolved and back side fist lift ex.no.change 75 and 901 intercom issue resolved need to change port no. 0113 old port faulty 0017</td><td></td></tr><tr><td>10-04-2024 10:29:56</td><td>Ravi Rajbhar</td><td>New</td><td></td><td>-</td></tr></tbody></table>					Date Time	Technician Name	Status	Remark	Sign	10-04-2024 06:05:40	Ravi Rajbhar	Completed	society office intercom issue resolved and ok working done and flat no.702 intercom issue resolved and back side fist lift ex.no.change 75 and 901 intercom issue resolved need to change port no. 0113 old port faulty 0017		10-04-2024 10:29:56	Ravi Rajbhar	New		-
Date Time	Technician Name	Status	Remark	Sign																
10-04-2024 06:05:40	Ravi Rajbhar	Completed	society office intercom issue resolved and ok working done and flat no.702 intercom issue resolved and back side fist lift ex.no.change 75 and 901 intercom issue resolved need to change port no. 0113 old port faulty 0017																	
10-04-2024 10:29:56	Ravi Rajbhar	New		-																
Previous Complain History :	<table><thead><tr><th>Date Time</th><th>Technician Name</th><th>Remark</th></tr></thead><tbody><tr><td>23-04-2024 05:07:45</td><td></td><td></td></tr><tr><td>18-04-2024 03:46:20</td><td>Ravi Rajbhar</td><td>society office intercom ok working already 702 intercom ok working already check our side 806 intercom issue resolved and ok working done checking cable flat to duct duct to junction box then repunching and 505 client not approve in flat client told next time</td></tr></tbody></table>					Date Time	Technician Name	Remark	23-04-2024 05:07:45			18-04-2024 03:46:20	Ravi Rajbhar	society office intercom ok working already 702 intercom ok working already check our side 806 intercom issue resolved and ok working done checking cable flat to duct duct to junction box then repunching and 505 client not approve in flat client told next time						
Date Time	Technician Name	Remark																		
23-04-2024 05:07:45																				
18-04-2024 03:46:20	Ravi Rajbhar	society office intercom ok working already 702 intercom ok working already check our side 806 intercom issue resolved and ok working done checking cable flat to duct duct to junction box then repunching and 505 client not approve in flat client told next time																		