




# Vallabh Enterprises

Regd. Office : 401,shanti kutir,shivaji road,near thakur international school,kandivali(west) mumbai - 400067  
Support : | W : www.vallabhenterprises.com  
E : vallabhsecure@yahoo.co.in

<b>Service Status Details : VE11447</b>																				
<b>Priority :</b>	Low																			
<b>Created By :</b>	Admin - Apurva Vajaria																			
<b>Complaint Mob. No. :</b>	9892982500																			
<b>Technician Name :</b>	Ravi Rajbhar		<b>Technician Mobile :</b>	8080922965																
<b>Ticket Type :</b>	Complain	<b>Date &amp; Time :</b>	23-04-2024 05:07:45																	
<b>Vendor Details :</b>																				
Company Name/Client Name :	Lifescapes Mirage	Customer's Mobile :	9892982500	Name :	Rakesh Sanghavi															
<b>Address :</b>																				
Mumbai , , , 400028 , Maharashtra																				
<b>AMC Details :</b>																				
Expiry Date :	01-01-1970 05:30:00		Type :																	
<b>Product Name :</b>	cCTV-Intercom																			
<b>Complain :</b>	society office intercom getting on off and society office camera not capturing lower side angle need to do survey for the same																			
<b>Technician Comment :</b>	society office intercom on off issue resolved and ok working done and ok camera survey done																			
<b>Complain Operator :</b>	Desktop - Apurva Vajaria																			
<b>Remark :</b>	society office intercom on off issue resolved and ok working done and ok camera survey done																			
<b>Status History :</b>	<table><thead><tr><th>Date Time</th><th>Technician Name</th><th>Status</th><th>Remark</th><th>Sign</th></tr></thead><tbody><tr><td>30-04-2024 01:08:33</td><td>Ravi Rajbhar</td><td>Completed</td><td>society office intercom on off issue resolved and ok working done and ok camera survey done</td><td></td></tr><tr><td>30-04-2024 10:39:41</td><td>Ravi Rajbhar</td><td>New</td><td></td><td>-</td></tr></tbody></table>					Date Time	Technician Name	Status	Remark	Sign	30-04-2024 01:08:33	Ravi Rajbhar	Completed	society office intercom on off issue resolved and ok working done and ok camera survey done		30-04-2024 10:39:41	Ravi Rajbhar	New		-
Date Time	Technician Name	Status	Remark	Sign																
30-04-2024 01:08:33	Ravi Rajbhar	Completed	society office intercom on off issue resolved and ok working done and ok camera survey done																	
30-04-2024 10:39:41	Ravi Rajbhar	New		-																
<b>Previous Complain History :</b>	<table><thead><tr><th>Date Time</th><th>Technician Name</th><th>Remark</th></tr></thead><tbody><tr><td>30-04-2024 10:42:48</td><td>Ravi Rajbhar</td><td>society office new phone install with new programming new port no.0140 and society office phone remove and install in lift and flat 1101 intercom issue resolved but instrument issue check our side</td></tr><tr><td>18-04-2024 03:46:20</td><td>Ravi Rajbhar</td><td>society office intercom ok working already 702 intercom ok working already check our side 806 intercom issue resolved and ok working done checking cable flat to duct duct to junction box then repunchiing and 505 client not approve in flat client told next time</td></tr></tbody></table>					Date Time	Technician Name	Remark	30-04-2024 10:42:48	Ravi Rajbhar	society office new phone install with new programming new port no.0140 and society office phone remove and install in lift and flat 1101 intercom issue resolved but instrument issue check our side	18-04-2024 03:46:20	Ravi Rajbhar	society office intercom ok working already 702 intercom ok working already check our side 806 intercom issue resolved and ok working done checking cable flat to duct duct to junction box then repunchiing and 505 client not approve in flat client told next time						
Date Time	Technician Name	Remark																		
30-04-2024 10:42:48	Ravi Rajbhar	society office new phone install with new programming new port no.0140 and society office phone remove and install in lift and flat 1101 intercom issue resolved but instrument issue check our side																		
18-04-2024 03:46:20	Ravi Rajbhar	society office intercom ok working already 702 intercom ok working already check our side 806 intercom issue resolved and ok working done checking cable flat to duct duct to junction box then repunchiing and 505 client not approve in flat client told next time																		