




# Vallabh Enterprises

Regd. Office : 401,shanti kutir,shivaji road,near thakur international school,kandivali(west) mumbai - 400067  
Support : | W : www.vallabhenterprises.com  
E : vallabhsecure@yahoo.co.in

<b>Service Status Details : VE9119</b>																				
<b>Priority :</b>	Low																			
<b>Created By :</b>	Admin - Apurva Vajaria																			
<b>Complaint Mob. No. :</b>	9892982500																			
<b>Technician Name :</b>	Atique Salmani		<b>Technician Mobile :</b>	8080922984																
<b>Ticket Type :</b>	Complain	<b>Date &amp; Time :</b>	10-08-2023 11:39:52																	
<b>Vendor Details :</b>																				
Company Name/Client Name :	Lifescapes Mirage	Customer's Mobile :	9892982500	Name :	Rakesh Sanghavi															
<b>Address :</b>																				
Mumbai , , , 400028 , Maharashtra																				
<b>AMC Details :</b>																				
<b>Expiry Date :</b>	01-01-1970 05:30:00		<b>Type :</b>																	
<b>Product Name :</b>	cCTV-Intercom																			
<b>Complain :</b>	CCTV Survey need to do and Flat no. 1805/1806 - Intercom connection need to do																			
<b>Technician Comment :</b>	Back side wing if need to cover all flate door thennn to Add new cameras all floor 1805/6 cable duct to flate not available long time and 1103 connection done from instrument side and also duct side .																			
<b>Complain Operator :</b>	Desktop - Apurva Vajaria																			
<b>Remark :</b>	Back side wing if need to cover all flate door thennn to Add new cameras all floor 1805/6 cable duct to flate not available long time and 1103 connection done from instrument side and also duct side .																			
<b>Status History :</b>	<table><thead><tr><th>Date Time</th><th>Technician Name</th><th>Status</th><th>Remark</th><th>Sign</th></tr></thead><tbody><tr><td>10-08-2023 03:58:31</td><td>Atique Salmani</td><td>Completed</td><td>Back side wing if need to cover all flate door thennn to Add new cameras all floor 1805/6 cable duct to flate not available long time and 1103 connection done from instrument side and also duct side .</td><td></td></tr><tr><td>10-08-2023 11:39:58</td><td>Atique Salmani</td><td>New</td><td></td><td>-</td></tr></tbody></table>					Date Time	Technician Name	Status	Remark	Sign	10-08-2023 03:58:31	Atique Salmani	Completed	Back side wing if need to cover all flate door thennn to Add new cameras all floor 1805/6 cable duct to flate not available long time and 1103 connection done from instrument side and also duct side .		10-08-2023 11:39:58	Atique Salmani	New		-
Date Time	Technician Name	Status	Remark	Sign																
10-08-2023 03:58:31	Atique Salmani	Completed	Back side wing if need to cover all flate door thennn to Add new cameras all floor 1805/6 cable duct to flate not available long time and 1103 connection done from instrument side and also duct side .																	
10-08-2023 11:39:58	Atique Salmani	New		-																
<b>Previous Complain History :</b>	<table><thead><tr><th>Date Time</th><th>Technician Name</th><th>Remark</th></tr></thead><tbody><tr><td>22-08-2023 12:49:21</td><td>DilshadKhan</td><td>Dvr off issu Resolved and solve and recording so</td></tr><tr><td>07-08-2023 03:48:50</td><td>Atique Salmani</td><td>One lift camera vedeo cable faulty power ok 13:floor camera vedeo loss issue resolved by changed BNC dc becuz totally rushted working ok set angel working ok and 4 all lift intercom shifted .</td></tr></tbody></table>					Date Time	Technician Name	Remark	22-08-2023 12:49:21	DilshadKhan	Dvr off issu Resolved and solve and recording so	07-08-2023 03:48:50	Atique Salmani	One lift camera vedeo cable faulty power ok 13:floor camera vedeo loss issue resolved by changed BNC dc becuz totally rushted working ok set angel working ok and 4 all lift intercom shifted .						
Date Time	Technician Name	Remark																		
22-08-2023 12:49:21	DilshadKhan	Dvr off issu Resolved and solve and recording so																		
07-08-2023 03:48:50	Atique Salmani	One lift camera vedeo cable faulty power ok 13:floor camera vedeo loss issue resolved by changed BNC dc becuz totally rushted working ok set angel working ok and 4 all lift intercom shifted .																		