




Vallabh Enterprises

Regd. Office : 401,shanti kutir,shivaji road,near thakur international school,kandivali(west) mumbai - 400067
Support : | W : www.vallabhenterprises.com
E : vallabhsecure@yahoo.co.in

Service Status Details : VE1939																																													
Priority :	Low																																												
Created By :	Admin - Apurva Vajaria																																												
Complaint Mob. No. :	9920153982																																												
Technician Name :	Atique Salmani		Technician Mobile :	8080922984																																									
Ticket Type :	New Installation	Date & Time :	01-10-2020 06:20:28																																										
Vendor Details :																																													
Company Name/Client Name :	Shree Siddhivinayak Towers CHS LTD	Customer's Mobile :	9920153982	Name :	Rakesh Shah																																								
Address :																																													
Mumbai , Chikoowadi, Borivali West, Mumbai, Maharashtra, India , , 400092 , Maharashtra																																													
AMC Details :																																													
Expiry Date :	01-01-1970 05:30:00		Type :																																										
Product Name :	VDP																																												
Complain :	to give demo a/901 and b/704																																												
Technician Comment :	b704 intercom seprate installation but cable not on postion and also they have no need . also visit in B 603.a604 volume slow issue resolved also a502 same issue resolved working ok																																												
Complain Operator :	Desktop - Apurva Vajaria																																												
Remark :	b704 intercom seprate installation but cable not on postion and also they have no need . also visit in B 603.a604 volume slow issue resolved also a502 same issue resolved working ok																																												
Status History :	<table><thead><tr><th>Date Time</th><th>Technician Name</th><th>Status</th><th>Remark</th><th>Sign</th></tr></thead><tbody><tr><td>10-10-2020 01:00:53</td><td>Atique Salmani</td><td>Completed</td><td>b704 intercom seprate installation but cable not on postion and also they have no need . also visit in B 603.a604 volume slow issue resolved also a502 same issue resolved working ok</td><td></td></tr><tr><td>10-10-2020 11:32:58</td><td>Atique Salmani</td><td>New</td><td></td><td>-</td></tr><tr><td>05-10-2020 06:05:29</td><td>Atique Salmani</td><td>New</td><td></td><td>-</td></tr><tr><td>05-10-2020 04:55:08</td><td>Atique Salmani</td><td>New</td><td></td><td>-</td></tr><tr><td>05-10-2020 12:05:14</td><td>Atique Salmani</td><td>New</td><td></td><td>-</td></tr><tr><td>01-10-2020 06:20:47</td><td>Atique Salmani</td><td>New</td><td></td><td>-</td></tr><tr><td>01-10-2020 06:20:28</td><td>Atique Salmani</td><td>New</td><td></td><td>-</td></tr></tbody></table>					Date Time	Technician Name	Status	Remark	Sign	10-10-2020 01:00:53	Atique Salmani	Completed	b704 intercom seprate installation but cable not on postion and also they have no need . also visit in B 603.a604 volume slow issue resolved also a502 same issue resolved working ok		10-10-2020 11:32:58	Atique Salmani	New		-	05-10-2020 06:05:29	Atique Salmani	New		-	05-10-2020 04:55:08	Atique Salmani	New		-	05-10-2020 12:05:14	Atique Salmani	New		-	01-10-2020 06:20:47	Atique Salmani	New		-	01-10-2020 06:20:28	Atique Salmani	New		-
Date Time	Technician Name	Status	Remark	Sign																																									
10-10-2020 01:00:53	Atique Salmani	Completed	b704 intercom seprate installation but cable not on postion and also they have no need . also visit in B 603.a604 volume slow issue resolved also a502 same issue resolved working ok																																										
10-10-2020 11:32:58	Atique Salmani	New		-																																									
05-10-2020 06:05:29	Atique Salmani	New		-																																									
05-10-2020 04:55:08	Atique Salmani	New		-																																									
05-10-2020 12:05:14	Atique Salmani	New		-																																									
01-10-2020 06:20:47	Atique Salmani	New		-																																									
01-10-2020 06:20:28	Atique Salmani	New		-																																									

Previous Complain History :			
	Date Time	Technician Name	Remark
	21-10-2020 11:21:32	Ravi Rajbhar	biometric attendance machine licences key update done and data download proper and one ueser dilit
	21-10-2020 11:20:17	Ravi Rajbhar	a wing 904. vdp screen faulty and return office and check