




# Vallabh Enterprises

Regd. Office : 401,shanti kutir,shivaji road,near thakur international school,kandivali(west) mumbai - 400067  
Support : | W : www.vallabhenterprises.com  
E : vallabhsecure@yahoo.co.in

<b>Service Status Details : VE2945</b>																									
<b>Priority :</b>	Low																								
<b>Created By :</b>	Admin - Apurva Vajaria																								
<b>Complaint Mob. No. :</b>	9920153982																								
<b>Technician Name :</b>	Ravi Rajbhar		<b>Technician Mobile :</b>	8080922965																					
<b>Ticket Type :</b>	Complain	<b>Date &amp; Time :</b>	05-04-2021 10:06:38																						
<b>Vendor Details :</b>																									
<b>Company Name/Client Name :</b>	Shree Siddhivinayak Towers CHS LTD	<b>Customer's Mobile :</b>	9920153982	<b>Name :</b>	Rakesh Shah																				
<b>Address :</b>																									
Mumbai , Chikoowadi, Borivali West, Mumbai, Maharashtra, India , , 400092 , Maharashtra																									
<b>AMC Details :</b>																									
<b>Expiry Date :</b>	01-01-1970 05:30:00		<b>Type :</b>																						
<b>Product Name :</b>	VDP																								
<b>Complain :</b>	Some flats vdp issue contact sufiyan																								
<b>Technician Comment :</b>	A wing 701, vdp ok working 1901 handset issue all working ok. B wing 1402, 1104, 1801, 1903 video issue solved and intercom issue resolved. 1004 electrician was not there																								
<b>Complain Operator :</b>	Desktop - Apurva Vajaria																								
<b>Remark :</b>	A wing 701, vdp ok working 1901 handset issue all working ok. B wing 1402, 1104, 1801, 1903 video issue solved and intercom issue resolved. 1004 electrician was not there																								
<b>Status History :</b>	<table><thead><tr><th>Date Time</th><th>Technician Name</th><th>Status</th><th>Remark</th><th>Sign</th></tr></thead><tbody><tr><td>05-04-2021 02:55:37</td><td>Ravi Rajbhar</td><td>Completed</td><td>A wing 701, vdp ok working 1901 handset issue all working ok. B wing 1402, 1104, 1801, 1903 video issue solved and intercom issue resolved. 1004 electrician was not there</td><td></td></tr><tr><td>05-04-2021 10:06:56</td><td>Ravi Rajbhar</td><td>New</td><td></td><td>-</td></tr><tr><td>05-04-2021 10:06:38</td><td>Ravi Rajbhar</td><td>New</td><td></td><td>-</td></tr></tbody></table>					Date Time	Technician Name	Status	Remark	Sign	05-04-2021 02:55:37	Ravi Rajbhar	Completed	A wing 701, vdp ok working 1901 handset issue all working ok. B wing 1402, 1104, 1801, 1903 video issue solved and intercom issue resolved. 1004 electrician was not there		05-04-2021 10:06:56	Ravi Rajbhar	New		-	05-04-2021 10:06:38	Ravi Rajbhar	New		-
Date Time	Technician Name	Status	Remark	Sign																					
05-04-2021 02:55:37	Ravi Rajbhar	Completed	A wing 701, vdp ok working 1901 handset issue all working ok. B wing 1402, 1104, 1801, 1903 video issue solved and intercom issue resolved. 1004 electrician was not there																						
05-04-2021 10:06:56	Ravi Rajbhar	New		-																					
05-04-2021 10:06:38	Ravi Rajbhar	New		-																					
<b>Previous Complain History :</b>	<table><thead><tr><th>Date Time</th><th>Technician Name</th><th>Remark</th></tr></thead><tbody><tr><td>25-06-2022 01:33:48</td><td>Ravi Rajbhar</td><td>a wing 304 b wing 303, 203 intercom issue resolved and ok working done inform to sufiyan sir with check</td></tr><tr><td>20-01-2022 02:36:45</td><td>ChandanYadav</td><td>A203 and A502 working ok . society office work completed . Intercom system a wing to b wing working ok.</td></tr></tbody></table>					Date Time	Technician Name	Remark	25-06-2022 01:33:48	Ravi Rajbhar	a wing 304 b wing 303, 203 intercom issue resolved and ok working done inform to sufiyan sir with check	20-01-2022 02:36:45	ChandanYadav	A203 and A502 working ok . society office work completed . Intercom system a wing to b wing working ok.											
Date Time	Technician Name	Remark																							
25-06-2022 01:33:48	Ravi Rajbhar	a wing 304 b wing 303, 203 intercom issue resolved and ok working done inform to sufiyan sir with check																							
20-01-2022 02:36:45	ChandanYadav	A203 and A502 working ok . society office work completed . Intercom system a wing to b wing working ok.																							