




# Vallabh Enterprises

Regd. Office : 401,shanti kutir,shivaji road,near thakur international school,kandivali(west) mumbai - 400067  
Support : | W : www.vallabhenterprises.com  
E : vallabhsecure@yahoo.co.in

<b>Service Status Details : VE5650</b>																									
<b>Priority :</b>	Low																								
<b>Created By :</b>	Admin - Apurva Vajaria																								
<b>Complaint Mob. No. :</b>	9892625683																								
<b>Technician Name :</b>	Siddhesh Chavan		<b>Technician Mobile :</b>	8080922985																					
<b>Ticket Type :</b>	Complain	<b>Date &amp; Time :</b>	06-06-2022 10:18:38																						
<b>Vendor Details :</b>																									
<b>Company Name/Client Name :</b>	Girish Pandya (raksha Pandya)	<b>Customer's Mobile :</b>	9892625683	<b>Name :</b>	Raksha Pandya																				
<b>Address :</b>																									
mumbai , , , 400067 , Maharashtra																									
<b>AMC Details :</b>																									
<b>Expiry Date :</b>	01-01-1970 05:30:00		<b>Type :</b>																						
<b>Product Name :</b>	VDP																								
<b>Complain :</b>	vdp getting blank issue																								
<b>Technician Comment :</b>	vdp off and on bell issue resolved and vdp under observation and memory card format out door camera and dome camera working ok																								
<b>Complain Operator :</b>	Desktop - Apurva Vajaria																								
<b>Remark :</b>	vdp off and on bell issue resolved and vdp under observation and memory card format out door camera and dome camera working ok																								
<b>Status History :</b>	<table><thead><tr><th>Date Time</th><th>Technician Name</th><th>Status</th><th>Remark</th><th>Sign</th></tr></thead><tbody><tr><td>06-06-2022 05:35:53</td><td>Siddhesh Chavan</td><td>Completed</td><td>vdp off and on bell issue resolved and vdp under observation and memory card format out door camera and dome camera working ok</td><td></td></tr><tr><td>06-06-2022 10:19:02</td><td>Siddhesh Chavan</td><td>New</td><td></td><td>-</td></tr><tr><td>06-06-2022 10:18:38</td><td>Siddhesh Chavan</td><td>New</td><td></td><td>-</td></tr></tbody></table>					Date Time	Technician Name	Status	Remark	Sign	06-06-2022 05:35:53	Siddhesh Chavan	Completed	vdp off and on bell issue resolved and vdp under observation and memory card format out door camera and dome camera working ok		06-06-2022 10:19:02	Siddhesh Chavan	New		-	06-06-2022 10:18:38	Siddhesh Chavan	New		-
Date Time	Technician Name	Status	Remark	Sign																					
06-06-2022 05:35:53	Siddhesh Chavan	Completed	vdp off and on bell issue resolved and vdp under observation and memory card format out door camera and dome camera working ok																						
06-06-2022 10:19:02	Siddhesh Chavan	New		-																					
06-06-2022 10:18:38	Siddhesh Chavan	New		-																					
<b>Previous Complain History :</b>	<table><thead><tr><th>Date Time</th><th>Technician Name</th><th>Remark</th></tr></thead><tbody><tr><td>30-04-2022 05:13:31</td><td>Siddhesh Chavan</td><td>vdp hang issue resolved and sd card is not view to vdp and vdp system default and resetting and vdp working ok 750 rs cash received</td></tr><tr><td>26-11-2021 11:42:17</td><td>YogeshDesai</td><td>vdp bell issue sloved continuous bell ringing has been stopped. pcb was faulty . new pcb has been installed vdp working fine</td></tr></tbody></table>					Date Time	Technician Name	Remark	30-04-2022 05:13:31	Siddhesh Chavan	vdp hang issue resolved and sd card is not view to vdp and vdp system default and resetting and vdp working ok 750 rs cash received	26-11-2021 11:42:17	YogeshDesai	vdp bell issue sloved continuous bell ringing has been stopped. pcb was faulty . new pcb has been installed vdp working fine											
Date Time	Technician Name	Remark																							
30-04-2022 05:13:31	Siddhesh Chavan	vdp hang issue resolved and sd card is not view to vdp and vdp system default and resetting and vdp working ok 750 rs cash received																							
26-11-2021 11:42:17	YogeshDesai	vdp bell issue sloved continuous bell ringing has been stopped. pcb was faulty . new pcb has been installed vdp working fine																							