







Vallabh Enterprises

Regd. Office : 401,shanti kutir,shivaji road,near thakur international school,kandivali(west) mumbai - 400067
Support : | W : www.vallabhenterprises.com
E : vallabhsecure@yahoo.co.in

Service Status Details : VE14277																														
Priority :	Low																													
Created By :	Admin - Apurva Vajaria																													
Complaint Mob. No. :	9987081703																													
Technician Name :	Ravi Rajbhar		Technician Mobile :	8080922965																										
Ticket Type :	Complain	Date & Time :	12-03-2025 05:22:28																											
Vendor Details :																														
Company Name/Client Name :	Armstrong Constructions Goregaon	Customer's Mobile :	9987081703	Name :	Rashmi																									
Address :																														
Mumbai , , , , Maharashtra																														
AMC Details :																														
Expiry Date :	01-01-1970 05:30:00		Type :																											
Product Name :	cCTV-Intercom																													
Complain :	1 camera and 1 intercom not working																													
Technician Comment :	One new camera install against faulty camera																													
Complain Operator :	Desktop - Apurva Vajaria																													
Remark :	One new camera install against faulty camera																													
Status History :	<table><thead><tr><th>Date Time</th><th>Technician Name</th><th>Status</th><th>Remark</th><th>Sign</th></tr></thead><tbody><tr><td>21-03-2025 05:50:35</td><td>Ravi Rajbhar</td><td>Completed</td><td>One new camera install against faulty camera</td><td></td></tr><tr><td>20-03-2025 06:46:34</td><td>Ravi Rajbhar</td><td>New</td><td></td><td>-</td></tr><tr><td>13-03-2025 11:39:54</td><td>Ravi Rajbhar</td><td>Work Pending</td><td>One cmaera issue remove cmaera and take to office And one intercom issue resolved and ok working done</td><td></td></tr><tr><td>13-03-2025 10:25:40</td><td>Ravi Rajbhar</td><td>New</td><td></td><td>-</td></tr></tbody></table>					Date Time	Technician Name	Status	Remark	Sign	21-03-2025 05:50:35	Ravi Rajbhar	Completed	One new camera install against faulty camera		20-03-2025 06:46:34	Ravi Rajbhar	New		-	13-03-2025 11:39:54	Ravi Rajbhar	Work Pending	One cmaera issue remove cmaera and take to office And one intercom issue resolved and ok working done		13-03-2025 10:25:40	Ravi Rajbhar	New		-
Date Time	Technician Name	Status	Remark	Sign																										
21-03-2025 05:50:35	Ravi Rajbhar	Completed	One new camera install against faulty camera																											
20-03-2025 06:46:34	Ravi Rajbhar	New		-																										
13-03-2025 11:39:54	Ravi Rajbhar	Work Pending	One cmaera issue remove cmaera and take to office And one intercom issue resolved and ok working done																											
13-03-2025 10:25:40	Ravi Rajbhar	New		-																										
Previous Complain History :	<table><thead><tr><th>Date Time</th><th>Technician Name</th><th>Remark</th></tr></thead><tbody><tr><td>09-04-2025 12:59:59</td><td>Atique Salmani</td><td>Accounts no touch relay not trigger so changed new no touch working ok completed .</td></tr><tr><td>04-02-2025 01:38:26</td><td>Atique Salmani</td><td>One dome camera reinstalled working ok use self smps bec2 on dvr smps was add 2 camera so used saprete cameras and dvr smps working ok under observation.</td></tr></tbody></table>					Date Time	Technician Name	Remark	09-04-2025 12:59:59	Atique Salmani	Accounts no touch relay not trigger so changed new no touch working ok completed .	04-02-2025 01:38:26	Atique Salmani	One dome camera reinstalled working ok use self smps bec2 on dvr smps was add 2 camera so used saprete cameras and dvr smps working ok under observation.																
Date Time	Technician Name	Remark																												
09-04-2025 12:59:59	Atique Salmani	Accounts no touch relay not trigger so changed new no touch working ok completed .																												
04-02-2025 01:38:26	Atique Salmani	One dome camera reinstalled working ok use self smps bec2 on dvr smps was add 2 camera so used saprete cameras and dvr smps working ok under observation.																												