




Vallabh Enterprises

Regd. Office : 401,shanti kutir,shivaji road,near thakur international school,kandivali(west) mumbai - 400067
Support : | W : www.vallabhenterprises.com
E : vallabhsecure@yahoo.co.in

Service Status Details : VE14225																				
Priority :	Low																			
Created By :	Admin - Apurva Vajaria																			
Complaint Mob. No. :	9821431296																			
Technician Name :	Ravi Rajbhar		Technician Mobile :	8080922965																
Ticket Type :	Complain	Date & Time :	06-03-2025 11:43:02																	
Vendor Details :																				
Company Name/Client Name :	SHETH BUILDERS PVT. LTD(SHETH SUPREME)	Customer's Mobile :	9821431296	Name :	Ratnesh Sir															
Address :																				
Mumbai , , , , Maharashtra																				
AMC Details :																				
Expiry Date :	01-01-1970 05:30:00		Type :																	
Product Name :	Intercom																			
Complain :	flat no. 1404/1004/905/804/701/602/605/506/404/405/301/306/202/101/103/1206 - Total 16 flats intercom issue and cctv some recording issue																			
Technician Comment :	1404 ok working 1205 ok working 1206 ok working 1102 ok working 1004 ok working 905 cable cut duct side 804 door lock 701 cable cut duct side 602 ok working 605 ok working 506 client say next time check 404 line ok no instrument 405 line ok instrument keypaid issue 301 door lock 306 ok working 302 ok working 202 line ok instrument remove client side 101 line ok no instrument 103 door lock																			
Complain Operator :	Desktop - Apurva Vajaria																			
Remark :	1404 ok working 1205 ok working 1206 ok working 1102 ok working 1004 ok working 905 cable cut duct side 804 door lock 701 cable cut duct side 602 ok working 605 ok working 506 client say next time check 404 line ok no instrument 405 line ok instrument keypaid issue 301 door lock 306 ok working 302 ok working 202 line ok instrument remove client side 101 line ok no instrument 103 door lock																			
Status History :	<table><thead><tr><th>Date Time</th><th>Technician Name</th><th>Status</th><th>Remark</th><th>Sign</th></tr></thead><tbody><tr><td>08-03-2025 05:36:07</td><td>Ravi Rajbhar</td><td>Completed</td><td>1404 ok working 1205 ok working 1206 ok working 1102 ok working 1004 ok working 905 cable cut duct side 804 door lock 701 cable cut duct side 602 ok working 605 ok working 506 client say next time check 404 line ok no instrument 405 line ok instrument keypaid issue 301 door lock 306 ok working 302 ok working 202 line ok instrument remove client side 101 line ok no instrument 103 door lock</td><td></td></tr><tr><td>07-03-2025 12:05:21</td><td>Ravi Rajbhar</td><td>New</td><td></td><td>-</td></tr></tbody></table>					Date Time	Technician Name	Status	Remark	Sign	08-03-2025 05:36:07	Ravi Rajbhar	Completed	1404 ok working 1205 ok working 1206 ok working 1102 ok working 1004 ok working 905 cable cut duct side 804 door lock 701 cable cut duct side 602 ok working 605 ok working 506 client say next time check 404 line ok no instrument 405 line ok instrument keypaid issue 301 door lock 306 ok working 302 ok working 202 line ok instrument remove client side 101 line ok no instrument 103 door lock		07-03-2025 12:05:21	Ravi Rajbhar	New		-
Date Time	Technician Name	Status	Remark	Sign																
08-03-2025 05:36:07	Ravi Rajbhar	Completed	1404 ok working 1205 ok working 1206 ok working 1102 ok working 1004 ok working 905 cable cut duct side 804 door lock 701 cable cut duct side 602 ok working 605 ok working 506 client say next time check 404 line ok no instrument 405 line ok instrument keypaid issue 301 door lock 306 ok working 302 ok working 202 line ok instrument remove client side 101 line ok no instrument 103 door lock																	
07-03-2025 12:05:21	Ravi Rajbhar	New		-																

Previous Complain History :			
	Date Time	Technician Name	Remark
	30-01-2025 11:18:44	PravinJagade	Ground back gate bolt lock install working done. Work completed.
	15-01-2025 01:24:47	Ravi Rajbhar	1403 , 1301 , 601 ,1102 , 1103 intercom issue resolved and ok working done 701 cable missing need to check then start intercom cable cut duct side