

Vallabh Enterprises

Regd. Office : 401,shanti kutir,shivaji road,near thakur international school,kandivali(west) mumbai - 400067
Support : | W : www.vallabhenterprises.com
E : vallabhsecure@yahoo.co.in

Service Status Details : VE14397																				
Priority :	Low																			
Created By :	Admin - Apurva Vajaria																			
Complaint Mob. No. :	9821431296																			
Technician Name :	Ravi Rajbhar		Technician Mobile :	8080922965																
Ticket Type :	Complain	Date & Time :	02-04-2025 10:40:31																	
Vendor Details :																				
Company Name/Client Name :	SHETH BUILDERS PVT. LTD(SHETH SUPREME)	Customer's Mobile :	9821431296	Name :	Ratnesh Sir															
Address :																				
Mumbai , , , , Maharashtra																				
AMC Details :																				
Expiry Date :	01-01-1970 05:30:00		Type :																	
Product Name :	Intercom																			
Complain :	flat no. 1105/1103/1003/901/902 - intercom issue (9471046583)																			
Technician Comment :																				
Complain Operator :	Desktop - Apurva Vajaria																			
Remark :	1301 line ok instrument issue 1305 not used phone 1201 line ok instrument issue 1103 issue resolved 1105 cable missing sift cable 1003 next time asking client 901 cable missing 902 cable remove duct side 905 door lock 701 cable remove duct side 602 line ok instrument remove client side 501 door lock 506 line 402 line ok 404 door lock 405 line ok instrument issue keypaid 301 next time asking client 201 cable missing and telephone remove also juct 202 not uesd phone 101 phone missing 103 issue resolved																			
Status History :	<table><thead><tr><th>Date Time</th><th>Technician Name</th><th>Status</th><th>Remark</th><th>Sign</th></tr></thead><tbody><tr><td>04-04-2025 11:07:25</td><td>Ravi Rajbhar</td><td>Completed</td><td></td><td>-</td></tr><tr><td>02-04-2025 10:40:37</td><td>Ravi Rajbhar</td><td>New</td><td></td><td>-</td></tr></tbody></table>					Date Time	Technician Name	Status	Remark	Sign	04-04-2025 11:07:25	Ravi Rajbhar	Completed		-	02-04-2025 10:40:37	Ravi Rajbhar	New		-
Date Time	Technician Name	Status	Remark	Sign																
04-04-2025 11:07:25	Ravi Rajbhar	Completed		-																
02-04-2025 10:40:37	Ravi Rajbhar	New		-																
Previous Complain History :	<table><thead><tr><th>Date Time</th><th>Technician Name</th><th>Remark</th></tr></thead><tbody><tr><td>15-03-2025 05:15:35</td><td>Ravi Rajbhar</td><td>Access door bolt lock issue and lock remove and collatt to office Lock installation done by Ravi - 02.04.2025</td></tr><tr><td>06-03-2025 11:43:02</td><td>Ravi Rajbhar</td><td>1404 ok working 1205 ok working 1206 ok working 1102 ok working 1004 ok working 905 cable cut duct side 804 door lock 701 cable cut duct side 602 ok working 605 ok working 506 client say next time check 404 line ok no instrument 405 line ok instrument keypaid issue 301 door lock 306 ok working 302 ok working 202 line ok instrument remove client side 101 line ok no instrument 103 door lock</td></tr></tbody></table>					Date Time	Technician Name	Remark	15-03-2025 05:15:35	Ravi Rajbhar	Access door bolt lock issue and lock remove and collatt to office Lock installation done by Ravi - 02.04.2025	06-03-2025 11:43:02	Ravi Rajbhar	1404 ok working 1205 ok working 1206 ok working 1102 ok working 1004 ok working 905 cable cut duct side 804 door lock 701 cable cut duct side 602 ok working 605 ok working 506 client say next time check 404 line ok no instrument 405 line ok instrument keypaid issue 301 door lock 306 ok working 302 ok working 202 line ok instrument remove client side 101 line ok no instrument 103 door lock						
Date Time	Technician Name	Remark																		
15-03-2025 05:15:35	Ravi Rajbhar	Access door bolt lock issue and lock remove and collatt to office Lock installation done by Ravi - 02.04.2025																		
06-03-2025 11:43:02	Ravi Rajbhar	1404 ok working 1205 ok working 1206 ok working 1102 ok working 1004 ok working 905 cable cut duct side 804 door lock 701 cable cut duct side 602 ok working 605 ok working 506 client say next time check 404 line ok no instrument 405 line ok instrument keypaid issue 301 door lock 306 ok working 302 ok working 202 line ok instrument remove client side 101 line ok no instrument 103 door lock																		