


Vallabh Enterprises

Regd. Office : 401,shanti kutir,shivaji road,near thakur international school,kandivali(west) mumbai - 400067
Support : | W : www.vallabhenterprises.com
E : vallabhsecure@yahoo.co.in

Service Status Details : VE12503					
Priority :	Low				
Created By :	Admin - Apurva Vajaria				
Complaint Mob. No. :	7021671156				
Technician Name :	Atique Salmani		Technician Mobile :	8080922984	
Ticket Type :	AMC visiting	Date & Time :	22-08-2024 12:25:12		
Vendor Details :					
Company Name/Client Name :	Lokhandwala Foundation	Customer's Mobile :	7021671156	Name :	Rauf Sir
Address :					
Mumbai , , , , Maharashtra					
AMC Details :					
Expiry Date :	01-01-1970 05:30:00		Type :		
Product Name :	Ppm				
Complain :	CCTV/PA/EPABX PPM need to do				
Technician Comment :	Ppm of cctv pa system and also epbax done 2nd floor camera nmbr 4 cable faulty power not getting also ohms drop so camera off . 1st floor camera nmbr 4 reconnection done camera disturbance need to changed 2 camera cable swap from 7 nmbr dvr to 6 nmbr dvr And back side gate staircase bullet camera water inserted in camera so camera faulty so collect for chek .				
Complain Operator :	Desktop - Apurva Vajaria				
Remark :	Ppm of cctv pa system and also epbax done 2nd floor camera nmbr 4 cable faulty power not getting also ohms drop so camera off . 1st floor camera nmbr 4 reconnection done camera disturbance need to changed 2 camera cable swap from 7 nmbr dvr to 6 nmbr dvr And back side gate staircase bullet camera water inserted in camera so camera faulty so collect for chek .				

Status History :	Date Time	Technician Name	Status	Remark	Sign
	26-08-2024 12:32:35	Atique Salmani	Work Pending		-
	23-08-2024 05:15:52	Atique Salmani	Completed	Ppm of cctv pa system and also epbax done 2nd floor camera nmbr 4 cable faulty power not getting also ohms drop so camera off . 1st floor camera nmbr 4 reconnection done camera disturbance need to changed 2 camera cable swap from 7 nmbr dvr to 6 nmbr dvr And back side gate staircase bullet camera water inserted in camera so camera faulty so collect for chek .	
	23-08-2024 12:56:33	Atique Salmani	New		-
	22-08-2024 12:25:29	Atique Salmani	New		-
Previous Complain History :	Date Time	Technician Name	Remark		
	28-11-2024 10:39:51	Atique Salmani	Ppm done of cctv and pa systems and intercom Dvr number 2 hdd issue removed and hand over to rauf sir only live view in dvr nmbr 2 And dvr date n time reset Gr 4 Ground floor camera faulty need to changed 2 2nd floor camera nmbr 3power cable break .4 . And ohms didn't get .cameras of passages . 103 vedeo loss camera faulty need to changed . 4th floor staff room instrument key pad issue . Also 3rd floor instrument issue Second floor ok working propr 1st floor ok working ok And total camera 67 .		
	30-09-2024 01:17:16	Atique Salmani			