## Vallabh Enterprises

**Regd. Office** : 401,shanti kutir,shivaji road,near thakur international school,kandivali(west) mumbai - 400067 Support : | **W** : www.vallabhenterprises.com **E** : vallabhsecure@yahoo.co.in

Service Status Details : VE7383 **Priority** : LOW **Created By :** Admin - Apurva Vajaria Complaint 7021671156 Mob. No. : Technician Atique Salmani **Technician Mobile :** 8080922984 Name : Complain Date & Time : 17-01-2023 11:01:43 **Ticket Type :** Vendor Details : Lokhandwala Customer's Mobile : 7021671156 Rauf Sir Company Name : Name/Client Foundation Name : Address : Mumbai,,,, Maharashtra AMC Details : Expiry Date : 01-01-1970 05:30:00 Type : Product EPABX-cctv Name : 8-10 cameras off issue,2)DVR Hdd Error(Hdd Not Detecting) Issue,3)5-6 Cameras Blur Issue 4)PA **Complain** : System 5-6 Speaker Not Working (Awaaz Nahi Aa Raha He) 5)EPABX 3-4 Phone Lines Also Not Working And Airtel Line Need To Punch In EPABX -After 2 Need To Send Technician 20/1/23 4th floor Room nmbr 411 camera remooved BNC from dvr end and shit dvr nmbr 5 becz in 411 critical and in 4 dvr no hdd so swap room nmbr 411 camera. G10 checked camera end ohms not **Comment**: getting so check Dvr end check also changed BNC working ok. G1 camera missing G6 camera missing only housing cabling already new. Ground passage camera nmbr 4 fractuation issue resolved by reconnection. 2nd floor passage camera nmbr 3 reconnection working ok. 2nd floor room nmbr 208 ohms power ok Aftr reconnection it's on But camera faulty after some time it gone no vedeo so camera need to changed. 2nd floor computer room ohms not getting so changed BNC as vedeo balloon working ok. 21/1/23/Audo camera 3 no vedeo power ohms ok camera faulty All P.A system working ok 306 passage speaker slow need to changed. Ground passage camera nmbr 4 faulty bullet . 404 camera need to changed dome cabling new . Epbax 3 18/1/23 409 camera faulty power ohms ok 411 angel set clean lence 405 camera faulty. Complain Desktop - Apurva Vajaria **Operator** : 20/1/23 4th floor Room nmbr 411 camera remooved BNC from dvr end and shit dvr nmbr 5 becz in **Remark** : 411 critical and in 4 dvr no hdd so swap room nmbr 411 camera. G10 checked camera end ohms not getting so check Dvr end check also changed BNC working ok. G1 camera missing G6 camera missing only housing cabling already new . Ground passage camera nmbr 4 fractuation issue resolved by reconnection. 2nd floor passage camera nmbr 3 reconnection working ok. 2nd floor room nmbr 208 ohms power ok Aftr reconnection it's on But camera faulty.after some time it gone no vedeo so camera need to changed. 2nd floor computer room ohms not getting so changed BNC as vedeo balloon working ok. 21/1/23/Audo camera 3 no vedeo power ohms ok camera faulty All P.A system working ok 306 passage speaker slow need to changed . Ground passage camera nmbr 4 faulty bullet . 404 camera need to changed dome cabling new . Epbax 3 18/1/23 409 camera faulty power ohms ok 411 angel set clean lence 405 camera faulty.

Status History :	Date Time	Technician Name	Statu	s	Remark	Sign
	21-01-2023 04:56:32	Atique Salmani	Complete	ed	20/1/23 4th floor Room nmbr 411 camera remooved BNC from dvr end and shit dvr nmbr 5 becz in 411 critical and in 4 dvr no hdd so swap room nmbr 411 camera. G10 checked camera end ohms not getting so check Dvr end check also changed BNC working ok. G1 camera missing G6 camera missing only housing cabling already new . Ground passage camera nmbr 4 fractuation issue resolved by reconnection. 2nd floor passage camera nmbr 3 reconnection working ok. 2nd floor room nmbr 208 ohms power ok Aftr reconnection it's on But camera faulty.after some time it gone no vedeo so camera need to changed. 2nd floor computer room ohms not getting so changed BNC as vedeo balloon working ok. 21/1/23/Audo camera 3 no vedeo power ohms ok camera faulty All P.A system working ok 306 passage speaker slow need to changed . Ground passage camera nmbr 4 faulty bullet . 404 camera need to changed dome cabling new . Epbax 3 18/1/23 409 camera faulty power ohms ok 411 angel set clean lence 405 camera faulty .	- यत्त व
	21-01-2023 11:56:45	Atique Salmani	New			-
	20-01-2023 11:26:24	Atique Salmani	New			-
	17-01-2023 06:09:08	Atique Salmani	Work Pending		409 camera faulty power ohms ok 411 angel set clean lence 406 camera faulty power ohms ok. 404 camera power ohms ok reconnection working ok 402 camera waves reconnection but not resolved need to changed also camera blurr issue . G8 backside cable joint some where not gettings ohm . And dvr nmbr4 adaptor changed working ok hdd but after 30 mnts again error in hdd need to check hdd with dvr first hdd . 4th floor dvr without hdd only live .	Ŕ
	17-01-2023 11:01:53	Atique Salmani	New			-
Previous Complain History :	Date Time Technici		ian Name	n Name Remark		
	07-02-2023 02:00:01 Mu		/lunna Gupta		Airtel I need to be connected direct instrument . working properly.	
	01-02-2023 10:4	4:10 Ravi Ra	5		Panasonic epbax system check ex. No ok working done but co line issue bcz Panasonic systems basic card issue inform to Rauf sir two CO line working CO1/CO3 /MTNL or Aeritel	