Vallabh Enterprises

 $\label{eq:Regd.office:401,shanti kutir,shivaji road,near thakur international school,kandivali(west) mumbai - 400067 \\ \text{Support:} \mid \textbf{W}: www.vallabhenterprises.com \\ \textbf{E}: vallabhsecure@yahoo.co.in \\ \end{cases}$

Service Status Details : VE7567							
Priority:	Low						
Created By:	Admin - Apurva Vajaria						
Complaint Mob. No. :	7021671156						
Technician Name :	Munna Gupta		Technicia:	an Mobile 8080922982			
Ticket Type :	Complain Date & Time :		07-02-20	23 02:00:01			
Vendor Details :	-						
Company Name/Client Name :	Lokhandwala Foundation	Customer's Mobile :	7021671	156	Name :	Rauf Sir	
Address:							
Mumbai , , , , Maharashtra							
AMC Details :							
Expiry Date :	01-01-1970 05:30:00	Type:					
Product Name:	Intercom						
Complain:	airtel line need to connect						
Technician Comment :	Airtel I need to be connected direct instrument . working properly.						
Complain Operator :	Desktop - Apurva Vajaria						
Remark:	Airtel I need to be connected direct instrument . working properly.						
Status History:	Date Time	Technician Name	Status	Re	mark	Sign	
	07-02-2023 02:03:05	Munna Gupta	Completed		to be connected nent . working	ashine	
	07-02-2023 02:00:11	Munna Gupta	New			-	

Previous Complain History :	Date Time	Technician Name	Remark		
	01-02-2023 10:44:10	Ravi Rajbhar	Panasonic epbax system check ex. No ok working done but co line issue bcz Panasonic systems basic card issue inform to Rauf sir two CO line working CO1/CO3 /MTNL or Aeritel		
	17-01-2023 11:01:43	Atique Salmani	20/1/23 4th floor Room nmbr 411 camera remooved BNC from dvr end and shit dvr nmbr 5 becz in 411 critical and in 4 dvr no hdd so swap room nmbr 411 camera. G10 checked camera end ohms not getting so check Dvr end check also changed BNC working ok. G1 camera missing G6 camera missing only housing cabling already new . Ground passage camera nmbr 4 fractuation issue resolved by reconnection. 2nd floor passage camera nmbr 3 reconnection working ok. 2nd floor room nmbr 208 ohms power ok Aftr reconnection it's on But camera faulty.after some time it gone no vedeo so camera need to changed. 2nd floor computer room ohms not getting so changed BNC as vedeo balloon working ok. 21/1/23/Audo camera 3 no vedeo power ohms ok camera faulty All P.A system working ok 306 passage speaker slow need to changed . Ground passage camera nmbr 4 faulty bullet . 404 camera need to changed dome cabling new . Epbax 3 18/1/23 409 camera faulty power ohms ok 411 angel set clean lence 405 camera faulty .		