

Vallabh Enterprises

Regd. Office : 401,shanti kutir,shivaji road,near thakur international school,kandivali(west) mumbai - 400067
Support : | W : www.vallabhenterprises.com
E : vallabhsecure@yahoo.co.in

Service Status Details : VE8233																				
Priority :	Low																			
Created By :	Admin - Apurva Vajaria																			
Complaint Mob. No. :	7021671156																			
Technician Name :	Kalpesh Subhash Gurav			Technician Mobile :	8879684054															
Ticket Type :	Complain	Date & Time :	28-04-2023 05:03:43																	
Vendor Details :																				
Company Name/Client Name :	Lokhandwala Foundation	Customer's Mobile :	7021671156	Name :	Rauf Sir															
Address :																				
Mumbai , , , Maharashtra																				
AMC Details :																				
Expiry Date :	01-01-1970 05:30:00		Type :																	
Product Name :	EPABX																			
Complain :	EPABX reception some shifting done need to do punching																			
Technician Comment :	Free Counter Direct Line Disconnect and Swap Direct Line in MD Cabin Principal cabin intercom connection shift Director cabin ok. Principal PA Intercom Connection found the wire and turned on the line. The reception cable is not installed																			
Complain Operator :	Desktop - Apurva Vajaria																			
Remark :	Free Counter Direct Line Disconnect and Swap Direct Line in MD Cabin Principal cabin intercom connection shift Director cabin ok. Principal PA Intercom Connection found the wire and turned on the line. The reception cable is not installed																			
Status History :	<table border="1"><thead><tr><th>Date Time</th><th>Technician Name</th><th>Status</th><th>Remark</th><th>Sign</th></tr></thead><tbody><tr><td>28-04-2023 05:14:04</td><td>Kalpesh SubhashGurav</td><td>Completed</td><td>Free Counter Direct Line Disconnect and Swap Direct Line in MD Cabin Principal cabin intercom connection shift Director cabin ok. Principal PA Intercom Connection found the wire and turned on the line. The reception cable is not installed</td><td></td></tr><tr><td>28-04-2023 05:04:22</td><td>Kalpesh SubhashGurav</td><td>New</td><td></td><td>-</td></tr></tbody></table>					Date Time	Technician Name	Status	Remark	Sign	28-04-2023 05:14:04	Kalpesh SubhashGurav	Completed	Free Counter Direct Line Disconnect and Swap Direct Line in MD Cabin Principal cabin intercom connection shift Director cabin ok. Principal PA Intercom Connection found the wire and turned on the line. The reception cable is not installed		28-04-2023 05:04:22	Kalpesh SubhashGurav	New		-
Date Time	Technician Name	Status	Remark	Sign																
28-04-2023 05:14:04	Kalpesh SubhashGurav	Completed	Free Counter Direct Line Disconnect and Swap Direct Line in MD Cabin Principal cabin intercom connection shift Director cabin ok. Principal PA Intercom Connection found the wire and turned on the line. The reception cable is not installed																	
28-04-2023 05:04:22	Kalpesh SubhashGurav	New		-																

Previous Complain History :	Date Time	Technician Name	Remark
	04-05-2023 11:24:32	ChandanYadav	Intercom connection solve.
	21-04-2023 10:56:38	Ravi Rajbhar	Lokhandwala school Dvr no.1 12 camera ok working done and date and time set 4 camera off g5/g3/g9 Hdd normal 1 tb Recoding going on Dvr no.2 16 camera ok working done Date and time ok Hdd normal 1tb Recoding going on Dvr no.3 Dvr check 5 bnc connected No hdd in dvr or no camera viewing in dvr Dvr no.4 15 camera ok working done 1 camera off Date and time set Hdd normal 1tb Recoding going on Dvr no.5 16 camera ok working timing set Hdd normal 1tb Recoding going on Dvr no.6 15 camera ok working 1 camera off also missing camera Hdd normal 1tb Recoding going on Time set Dvr no.7 14 camera ok working 2 camera off Date and time set Hdd normal 1tb Recoding going on