

# Vallabh Enterprises

**Regd. Office :** 401,shanti kutir,shivaji road,near thakur international school,kandivali(west) mumbai - 400067  
**Support : | W :** www.vallabhenterprises.com  
**E :** vallabhsecure@yahoo.co.in

<b>Service Status Details : VE6806</b>															
<b>Priority :</b>	Low														
<b>Created By :</b>	Admin - Apurva Vajaria														
<b>Complaint Mob. No. :</b>	9820061834														
<b>Technician Name :</b>	Siddhesh Chavan		<b>Technician Mobile :</b>	8080922985											
<b>Ticket Type :</b>	Complain	<b>Date &amp; Time :</b>	10-11-2022 02:30:52												
<b>Vendor Details :</b>															
<b>Company Name/Client Name :</b>	Jainson Manufacturing Company Bosari	<b>Customer's Mobile :</b>	9820061834	<b>Name :</b>	Ritesh Bhai										
<b>Address :</b>															
Mumbai , , , , Maharashtra															
<b>AMC Details :</b>															
<b>Expiry Date :</b>	01-01-1970 05:30:00		<b>Type :</b>												
<b>Product Name :</b>	CCTV														
<b>Complain :</b>	1 camera off issue														
<b>Technician Comment :</b>															
<b>Complain Operator :</b>	Desktop - Apurva Vajaria														
<b>Remark :</b>															
<b>Status History :</b>	<table><thead><tr><th>Date Time</th><th>Technician Name</th><th>Status</th><th>Remark</th><th>Sign</th></tr></thead><tbody><tr><td>10-11-2022 02:31:01</td><td>Siddhesh Chavan</td><td>New</td><td></td><td>-</td></tr></tbody></table>					Date Time	Technician Name	Status	Remark	Sign	10-11-2022 02:31:01	Siddhesh Chavan	New		-
Date Time	Technician Name	Status	Remark	Sign											
10-11-2022 02:31:01	Siddhesh Chavan	New		-											
<b>Previous Complain History :</b>	<table><thead><tr><th>Date Time</th><th>Technician Name</th><th>Remark</th></tr></thead><tbody><tr><td>12-01-2023 08:26:46</td><td>Siddhesh Chavan</td><td>10 phone install and total 11 phone concted and working and all phone numbering done and 7 line io not install and 2 camera repair and ruten to Anu sir</td></tr><tr><td>08-07-2022 12:48:59</td><td>Anil Yadav</td><td>[12/07, 20:24] Anil Yadav: Work update. 1) 39 cameras started and all (47) cameras ip sequence with angal set . 2) IO punch and plate installed- 15 point. 3) patch panel installed 24 port. 4) All point working fine testing with sharuk. 5) Access point installed working condition. 6) Teliphone jack installed - 7 nos. 7) Teliphone line testing working condition. 8) Hdmi extender and switcher installed. 9) Nvr online done and details sent Ritesh sir. 10) Ground floor 5 cable short cable joined. [12/07, 20:33] Anil Yadav: 1) IO punch and teliphone line 3 point at pending because of carpenter. 2) Lift camera not installed because of liftman.</td></tr></tbody></table>					Date Time	Technician Name	Remark	12-01-2023 08:26:46	Siddhesh Chavan	10 phone install and total 11 phone concted and working and all phone numbering done and 7 line io not install and 2 camera repair and ruten to Anu sir	08-07-2022 12:48:59	Anil Yadav	[12/07, 20:24] Anil Yadav: Work update. 1) 39 cameras started and all (47) cameras ip sequence with angal set . 2) IO punch and plate installed- 15 point. 3) patch panel installed 24 port. 4) All point working fine testing with sharuk. 5) Access point installed working condition. 6) Teliphone jack installed - 7 nos. 7) Teliphone line testing working condition. 8) Hdmi extender and switcher installed. 9) Nvr online done and details sent Ritesh sir. 10) Ground floor 5 cable short cable joined. [12/07, 20:33] Anil Yadav: 1) IO punch and teliphone line 3 point at pending because of carpenter. 2) Lift camera not installed because of liftman.	
Date Time	Technician Name	Remark													
12-01-2023 08:26:46	Siddhesh Chavan	10 phone install and total 11 phone concted and working and all phone numbering done and 7 line io not install and 2 camera repair and ruten to Anu sir													
08-07-2022 12:48:59	Anil Yadav	[12/07, 20:24] Anil Yadav: Work update. 1) 39 cameras started and all (47) cameras ip sequence with angal set . 2) IO punch and plate installed- 15 point. 3) patch panel installed 24 port. 4) All point working fine testing with sharuk. 5) Access point installed working condition. 6) Teliphone jack installed - 7 nos. 7) Teliphone line testing working condition. 8) Hdmi extender and switcher installed. 9) Nvr online done and details sent Ritesh sir. 10) Ground floor 5 cable short cable joined. [12/07, 20:33] Anil Yadav: 1) IO punch and teliphone line 3 point at pending because of carpenter. 2) Lift camera not installed because of liftman.													