Vallabh Enterprises

 $\label{eq:Regd.office:401,shanti kutir,shivaji road,near thakur international school,kandivali(west) mumbai - 400067 \\ \text{Support:} \mid \textbf{W}: www.vallabhenterprises.com \\ \textbf{E}: vallabhsecure@yahoo.co.in \\ \end{cases}$

Service Status De	tails: VE7356						
Priority:	Low						
Created By:	Admin - Apurva Vajaria						
Complaint Mob.	9820061834						
Technician Name :	Siddhesh Chavan			Technician Mobile :		8080922985	
Ticket Type :	New Installation	Date & Time	:	12-01-2023 08:26:46			
Vendor Details :							
Company Name/Client Name :	Jainson Manufacturing Company Bosari	Customer's Mobile :		9820061834		Name :	Ritesh Bhai
Address:							
Mumbai , , , , Mal	harashtra						
AMC Details :							
Expiry Date :	01-01-1970 05:30:00			Type:			
Product Name:	EPABX-cctv						
Complain:	Phone installed need list exst no repiar camera						
Technician Comment :	10 phone install and total 11 phone concted and working and all phone numbering done and 7 line io not install and 2 camera repair and ruten to Anu sir						
Complain Operator :	Desktop - Apurva Vajaria						
Remark:	10 phone install and total 11 phone concted and working and all phone numbering done and 7 line io not install and 2 camera repair and ruten to Anu sir						
Status History :	Date Time	Technician Name	Sta	atus	Re	mark	Sign
	12-01-2023 08:32:34	Siddhesh Chavan	Work Pendi		10 phone insta phone concted and all phone a and 7 line io no camera repair Anu sir	and working numbering done ot install and 2	
	12-01-2023 08:26:59	Siddhesh Chavan	New				-

Previous Complain History :	Date Time	Technician Name	Remark		
	10-11-2022 02:30:52	Siddhesh Chavan			
	08-07-2022 12:48:59	Anil Yadav	[12/07, 20:24] Anil Yadav: Work update. 1) 39 cameras started and all (47) cameras ip sequence with angal set . 2) IO punch and plate installed- 15 point. 3) patch panel installed 24 port. 4) All point working fine testing with sharuk. 5) Access point installed working condition. 6) Teliphone jack installed - 7 nos. 7) Teliphone line testing working condition. 8) Hdmi extender and switcher installed. 9) Nvr online done and details sent Ritesh sir. 10) Ground floor 5 cable short cable joined. [12/07, 20:33] Anil Yadav: 1) IO punch and teliphone line 3 point at pending because of carpenter. 2) Lift camera not installed because of liftman.		