







# Vallabh Enterprises

Regd. Office : 401,shanti kutir,shivaji road,near thakur international school,kandivali(west) mumbai - 400067  
Support : | W : www.vallabhenterprises.com  
E : vallabhsecure@yahoo.co.in

<b>Service Status Details : VE6725</b>																														
<b>Priority :</b>	Low																													
<b>Created By :</b>	Admin - Apurva Vajaria																													
<b>Complaint Mob. No. :</b>	9820061834																													
<b>Technician Name :</b>	Ravi Rajbhar		<b>Technician Mobile :</b>	8080922965																										
<b>Ticket Type :</b>	New Installation	<b>Date &amp; Time :</b>	02-11-2022 11:16:32																											
<b>Vendor Details :</b>																														
Company Name/Client Name :	Jainson Kandivali East	Customer's Mobile :	9820061834	Name :	Ritesh Sir Oberoi																									
<b>Address :</b>																														
Mumbai , , , , Maharashtra																														
<b>AMC Details :</b>																														
Expiry Date :	01-01-1970 05:30:00		Type :																											
<b>Product Name :</b>	Time And Attendance																													
<b>Complain :</b>	new machine installation																													
<b>Technician Comment :</b>	new biometric attendance machine also install and ok working done and lincenc key update today with cabling 10 meter router to divice divice ip 192.168.1.201 password 3107																													
<b>Complain Operator :</b>	Desktop - Apurva Vajaria																													
<b>Remark :</b>	new biometric attendance machine also install and ok working done and lincenc key update today with cabling 10 meter router to divice divice ip 192.168.1.201 password 3107																													
<b>Status History :</b>	<table><thead><tr><th>Date Time</th><th>Technician Name</th><th>Status</th><th>Remark</th><th>Sign</th></tr></thead><tbody><tr><td>07-11-2022 12:37:23</td><td>Ravi Rajbhar</td><td>Completed</td><td>new biometric attendance machine also install and ok working done and lincenc key update today with cabling 10 meter router to divice divice ip 192.168.1.201 password 3107</td><td></td></tr><tr><td>07-11-2022 10:32:19</td><td>Ravi Rajbhar</td><td>New</td><td></td><td>-</td></tr><tr><td>02-11-2022 04:13:02</td><td>Ravi Rajbhar</td><td>Work Pending</td><td>new biometric attendance divice install done etimetrack light software install with configuration done license key update wark pending</td><td></td></tr><tr><td>02-11-2022 11:16:38</td><td>Ravi Rajbhar</td><td>New</td><td></td><td>-</td></tr></tbody></table>					Date Time	Technician Name	Status	Remark	Sign	07-11-2022 12:37:23	Ravi Rajbhar	Completed	new biometric attendance machine also install and ok working done and lincenc key update today with cabling 10 meter router to divice divice ip 192.168.1.201 password 3107		07-11-2022 10:32:19	Ravi Rajbhar	New		-	02-11-2022 04:13:02	Ravi Rajbhar	Work Pending	new biometric attendance divice install done etimetrack light software install with configuration done license key update wark pending		02-11-2022 11:16:38	Ravi Rajbhar	New		-
Date Time	Technician Name	Status	Remark	Sign																										
07-11-2022 12:37:23	Ravi Rajbhar	Completed	new biometric attendance machine also install and ok working done and lincenc key update today with cabling 10 meter router to divice divice ip 192.168.1.201 password 3107																											
07-11-2022 10:32:19	Ravi Rajbhar	New		-																										
02-11-2022 04:13:02	Ravi Rajbhar	Work Pending	new biometric attendance divice install done etimetrack light software install with configuration done license key update wark pending																											
02-11-2022 11:16:38	Ravi Rajbhar	New		-																										

Previous Complain History :			
	Date Time	Technician Name	Remark
	14-09-2022 11:01:43	Siddhesh Chavan	tv viewing issue resolved and tv video port issue change video port and issue resolved
	20-08-2022 10:43:51	Atique Salmani	one cameras reconnection working ok and one cable joint find out and joint is near c 101 in junction so check cable continuity and rejoin now working ok.also one extention 25 issue resolved.