










Vallabh Enterprises

Regd. Office : 401,shanti kutir,shivaji road,near thakur international school,kandivali(west) mumbai - 400067
Support : | W : www.vallabhenterprises.com
E : vallabhsecure@yahoo.co.in

Service Status Details : VE4093					
Priority :	Low				
Created By :	Admin - Apurva Vajaria				
Complaint Mob. No. :	9029000445				
Technician Name :	Mayur Yadav		Technician Mobile :	8411951301	
Ticket Type :	New Installation	Date & Time :	22-10-2021 01:43:16		
Vendor Details :					
Company Name/Client Name :	Poonam Cluster	Customer's Mobile :	9029000445	Name :	Ritu Gupta
Address :					
Mumbai , , , , Maharashtra					
AMC Details :					
Expiry Date :	01-01-1970 05:30:00		Type :		
Product Name :	Access				
Complain :	Installation of boom Barrier				
Technician Comment :	boom barrier installation done photocell detector for car detection install both reader install panel install 10010 number tag install in car and 81 tags handover to Paul sir keys and remote handover to Paul sir network switch for computer handover to Paul sir require computer for software installation				
Complain Operator :	Desktop - Apurva Vajaria				
Remark :	boom barrier installation done photocell detector for car detection install both reader install panel install 10010 number tag install in car and 81 tags handover to Paul sir keys and remote handover to Paul sir network switch for computer handover to Paul sir require computer for software installation				

Status History :	<table><tr><th>Date Time</th><th>Technician Name</th><th>Status</th><th>Remark</th><th>Sign</th></tr><tr><td>30-10-2021 08:08:31</td><td>MayurYadav</td><td>Completed</td><td>boom barrier installation done photocell detector for car detection install both reader install panel install 10010 number tag install in car and 81 tags handover to Paul sir keys and remote handover to Paul sir network switch for computer handover to Paul sir require computer for software installation</td><td></td></tr><tr><td>30-10-2021 11:10:25</td><td>MayurYadav</td><td>New</td><td></td><td>-</td></tr><tr><td>28-10-2021 07:51:49</td><td>MayurYadav</td><td>In Progress</td><td>81 tags added in controller bracket fix</td><td></td></tr><tr><td>28-10-2021 05:48:33</td><td>MayurYadav</td><td>New</td><td></td><td>-</td></tr><tr><td>22-10-2021 07:13:05</td><td>MayurYadav</td><td>In Progress</td><td>70 mtrs cat6 cabling done photocell detector alignment check</td><td></td></tr><tr><td>22-10-2021 01:43:37</td><td>MayurYadav</td><td>New</td><td></td><td>-</td></tr><tr><td>22-10-2021 01:43:16</td><td>MayurYadav</td><td>New</td><td></td><td>-</td></tr></table>	Date Time	Technician Name	Status	Remark	Sign	30-10-2021 08:08:31	MayurYadav	Completed	boom barrier installation done photocell detector for car detection install both reader install panel install 10010 number tag install in car and 81 tags handover to Paul sir keys and remote handover to Paul sir network switch for computer handover to Paul sir require computer for software installation		30-10-2021 11:10:25	MayurYadav	New		-	28-10-2021 07:51:49	MayurYadav	In Progress	81 tags added in controller bracket fix		28-10-2021 05:48:33	MayurYadav	New		-	22-10-2021 07:13:05	MayurYadav	In Progress	70 mtrs cat6 cabling done photocell detector alignment check		22-10-2021 01:43:37	MayurYadav	New		-	22-10-2021 01:43:16	MayurYadav	New		-
	Date Time	Technician Name	Status	Remark	Sign																																				
	30-10-2021 08:08:31	MayurYadav	Completed	boom barrier installation done photocell detector for car detection install both reader install panel install 10010 number tag install in car and 81 tags handover to Paul sir keys and remote handover to Paul sir network switch for computer handover to Paul sir require computer for software installation																																					
	30-10-2021 11:10:25	MayurYadav	New		-																																				
	28-10-2021 07:51:49	MayurYadav	In Progress	81 tags added in controller bracket fix																																					
	28-10-2021 05:48:33	MayurYadav	New		-																																				
	22-10-2021 07:13:05	MayurYadav	In Progress	70 mtrs cat6 cabling done photocell detector alignment check																																					
	22-10-2021 01:43:37	MayurYadav	New		-																																				
22-10-2021 01:43:16	MayurYadav	New		-																																					
Previous Complain History :	<table><tr><th>Date Time</th><th>Technician Name</th><th>Remark</th></tr><tr><td>31-01-2022 10:23:36</td><td>Ravi Rajbhar</td><td></td></tr><tr><td>13-01-2022 10:04:10</td><td>MayurYadav</td><td></td></tr></table>				Date Time	Technician Name	Remark	31-01-2022 10:23:36	Ravi Rajbhar		13-01-2022 10:04:10	MayurYadav																													
	Date Time	Technician Name	Remark																																						
	31-01-2022 10:23:36	Ravi Rajbhar																																							
13-01-2022 10:04:10	MayurYadav																																								