

Vallabh Enterprises

Regd. Office : 401,shanti kutir,shivaji road,near thakur international school,kandivali(west) mumbai - 400067
Support : | W : www.vallabhenterprises.com
E : vallabhsecure@yahoo.co.in

Service Status Details : VE5249																									
Priority :	Low																								
Created By :	Admin - Apurva Vajaria																								
Complaint Mob. No. :	9029000445																								
Technician Name :	Ravi Rajbhar		Technician Mobile :	8080922965																					
Ticket Type :	Complain	Date & Time :	19-04-2022 02:47:47																						
Vendor Details :																									
Company Name/Client Name :	Poonam Cluster	Customer's Mobile :	9029000445	Name :	Ritu Gupta																				
Address :																									
Mumbai , , , , Maharashtra																									
AMC Details :																									
Expiry Date :	01-01-1970 05:30:00		Type :																						
Product Name :	Access																								
Complain :	boom Barrier p2 issue																								
Technician Comment :	P2/basements boom berriar check and ok working done inform to poal sir / security parson Niraj pathak and CCTV TV room new pc install with zk Access control 3.5 software install																								
Complain Operator :	Desktop - Apurva Vajaria																								
Remark :	P2/basements boom berriar check and ok working done inform to poal sir / security parson Niraj pathak and CCTV TV room new pc install with zk Access control 3.5 software install																								
Status History :	<table><thead><tr><th>Date Time</th><th>Technician Name</th><th>Status</th><th>Remark</th><th>Sign</th></tr></thead><tbody><tr><td>19-04-2022 07:13:08</td><td>Ravi Rajbhar</td><td>Completed</td><td>P2/basements boom berriar check and ok working done inform to poal sir / security parson Niraj pathak and CCTV TV room new pc install with zk Access control 3.5 software install</td><td></td></tr><tr><td>19-04-2022 03:34:04</td><td>Ravi Rajbhar</td><td>New</td><td></td><td>-</td></tr><tr><td>19-04-2022 02:47:47</td><td>Ravi Rajbhar</td><td>New</td><td></td><td>-</td></tr></tbody></table>					Date Time	Technician Name	Status	Remark	Sign	19-04-2022 07:13:08	Ravi Rajbhar	Completed	P2/basements boom berriar check and ok working done inform to poal sir / security parson Niraj pathak and CCTV TV room new pc install with zk Access control 3.5 software install		19-04-2022 03:34:04	Ravi Rajbhar	New		-	19-04-2022 02:47:47	Ravi Rajbhar	New		-
Date Time	Technician Name	Status	Remark	Sign																					
19-04-2022 07:13:08	Ravi Rajbhar	Completed	P2/basements boom berriar check and ok working done inform to poal sir / security parson Niraj pathak and CCTV TV room new pc install with zk Access control 3.5 software install																						
19-04-2022 03:34:04	Ravi Rajbhar	New		-																					
19-04-2022 02:47:47	Ravi Rajbhar	New		-																					
Previous Complain History :	<table><thead><tr><th>Date Time</th><th>Technician Name</th><th>Remark</th></tr></thead><tbody><tr><td>19-04-2022 02:44:48</td><td>Ravi Rajbhar</td><td>attended by sandeep - B3-801 intercom work done</td></tr><tr><td>13-04-2022 11:54:34</td><td>Ravi Rajbhar</td><td>B1- 1301 port change and new port used 062 line ok instrument issue B2- 1601 line ok instrument issue B2- 402 duct to flat cable issue need to cable change duct side line ok</td></tr></tbody></table>					Date Time	Technician Name	Remark	19-04-2022 02:44:48	Ravi Rajbhar	attended by sandeep - B3-801 intercom work done	13-04-2022 11:54:34	Ravi Rajbhar	B1- 1301 port change and new port used 062 line ok instrument issue B2- 1601 line ok instrument issue B2- 402 duct to flat cable issue need to cable change duct side line ok											
Date Time	Technician Name	Remark																							
19-04-2022 02:44:48	Ravi Rajbhar	attended by sandeep - B3-801 intercom work done																							
13-04-2022 11:54:34	Ravi Rajbhar	B1- 1301 port change and new port used 062 line ok instrument issue B2- 1601 line ok instrument issue B2- 402 duct to flat cable issue need to cable change duct side line ok																							