




# Vallabh Enterprises

Regd. Office : 401,shanti kutir,shivaji road,near thakur international school,kandivali(west) mumbai - 400067  
Support : | W : www.vallabhenterprises.com  
E : vallabhsecure@yahoo.co.in

<b>Service Status Details : VE6705</b>																				
<b>Priority :</b>	Low																			
<b>Created By :</b>	Admin - Apurva Vajaria																			
<b>Complaint Mob. No. :</b>	9029000455																			
<b>Technician Name :</b>	Ravi Rajbhar		<b>Technician Mobile :</b>	8080922965																
<b>Ticket Type :</b>	Complain	<b>Date &amp; Time :</b>	31-10-2022 03:43:54																	
<b>Vendor Details :</b>																				
<b>Company Name/Client Name :</b>	Poonam Cluster	<b>Customer's Mobile :</b>	9029000455	<b>Name :</b>	Ritu Gupta															
<b>Address :</b>																				
Mumbai , , , , Maharashtra																				
<b>AMC Details :</b>																				
<b>Expiry Date :</b>	01-01-1970 05:30:00		<b>Type :</b>																	
<b>Product Name :</b>	Intercom																			
<b>Complain :</b>	B2-1602 intercom issue B1-1805 intercom not working B3-701 intercom issue																			
<b>Technician Comment :</b>	B-1 1805 intercom ok working out door camera switch problem inform to presell mdm B2- 1602 out door camera switch problem B-3 701 cable missing in flat need to change new cable infrom to client																			
<b>Complain Operator :</b>	Desktop - Apurva Vajaria																			
<b>Remark :</b>	B-1 1805 intercom ok working out door camera switch problem inform to presell mdm B2- 1602 out door camera switch problem B-3 701 cable missing in flat need to change new cable infrom to client																			
<b>Status History :</b>	<table><thead><tr><th>Date Time</th><th>Technician Name</th><th>Status</th><th>Remark</th><th>Sign</th></tr></thead><tbody><tr><td>31-10-2022 04:40:06</td><td>Ravi Rajbhar</td><td>Completed</td><td>B-1 1805 intercom ok working out door camera switch problem inform to presell mdm B2- 1602 out door camera switch problem B-3 701 cable missing in flat need to change new cable infrom to client</td><td></td></tr><tr><td>31-10-2022 03:44:01</td><td>Ravi Rajbhar</td><td>New</td><td></td><td>-</td></tr></tbody></table>					Date Time	Technician Name	Status	Remark	Sign	31-10-2022 04:40:06	Ravi Rajbhar	Completed	B-1 1805 intercom ok working out door camera switch problem inform to presell mdm B2- 1602 out door camera switch problem B-3 701 cable missing in flat need to change new cable infrom to client		31-10-2022 03:44:01	Ravi Rajbhar	New		-
Date Time	Technician Name	Status	Remark	Sign																
31-10-2022 04:40:06	Ravi Rajbhar	Completed	B-1 1805 intercom ok working out door camera switch problem inform to presell mdm B2- 1602 out door camera switch problem B-3 701 cable missing in flat need to change new cable infrom to client																	
31-10-2022 03:44:01	Ravi Rajbhar	New		-																
<b>Previous Complain History :</b>	<table><thead><tr><th>Date Time</th><th>Technician Name</th><th>Remark</th></tr></thead><tbody><tr><td>01-11-2022 03:43:35</td><td>Ravi Rajbhar</td><td>back gate intercom issue resolved and b3 reception intercom issue resolved b1 main door em lock issue resolved but door closed very focus</td></tr><tr><td>28-10-2022 10:56:43</td><td>Shiva Meena</td><td></td></tr></tbody></table>					Date Time	Technician Name	Remark	01-11-2022 03:43:35	Ravi Rajbhar	back gate intercom issue resolved and b3 reception intercom issue resolved b1 main door em lock issue resolved but door closed very focus	28-10-2022 10:56:43	Shiva Meena							
Date Time	Technician Name	Remark																		
01-11-2022 03:43:35	Ravi Rajbhar	back gate intercom issue resolved and b3 reception intercom issue resolved b1 main door em lock issue resolved but door closed very focus																		
28-10-2022 10:56:43	Shiva Meena																			