Vallabh Enterprises

 $\label{eq:Regd.office:401,shanti kutir,shivaji road,near thakur international school,kandivali(west) mumbai - 400067 \\ \text{Support:} \mid \textbf{W}: www.vallabhenterprises.com \\ \textbf{E}: vallabhsecure@yahoo.co.in \\ \end{cases}$

Service Status I	Details : VE8156									
Priority:	Low									
Created By:	Admin - Apurva Vajaria									
Complaint Mob. No. :	9029000455									
Technician Name :	Atique Salmani		Technician Mobile :	8080922984						
Ticket Type :	Complain Date & Time :		19-04-2023 10:56:07):56:07						
Vendor Details :										
Company Name/Client Name :	Poonam Cluster	Customer's Mobile :	9029000455	Name :	Ritu Gupta					
Address:										
Mumbai,,,, Maharashtra										
AMC Details :										
Expiry Date :	01-01-1970 05:30:00		Type:							
Product Name:	CCTV									
Complain:	B1 - 503 camera need to shift only survey need to do B2 Lobby 7-8 camera off issue Main gate biometric machine need to take in network B2 P2 office outside camera angle need to change B3 Lobby when door closing some noise issue									
Technician Comment :	Poonam cluster 1."B1 - 503 camera need to shift 1 meter can shift without new cabling client need boath qoute if new cabling then cable 35/40 meter 2.B2 Lobby 7-8 camera off issue 5th floor refuge area 504 side duct Poe switch plug point remooved . 3.Main gate biometric machine need to take in network in device rj 45 connector missing also need 5 meter cat6 cable 4.B2 P2 office outside camera angle need to change set angel according to Mateen sir 5.B3 Lobby when door closing some noise issue" there is issue of door alignment I have told to supervisor for set by carpenter .									
Complain Operator :	Desktop - Apurva Vajaria									
Remark :	Poonam cluster 1."B1 - 503 camera need to shift 1 meter can shift without new cabling client need boath qoute if new cabling then cable $35/40$ meter 2.B2 Lobby 7-8 camera off issue 5 th floor refuge area 504 side duct Poe switch plug point remooved . 3 .Main gate biometric machine need to take in network in device rj 45 connector missing also need 5 meter cat 6 cable 4 .B2 P2 office outside camera angle need to change set angel according to Mateen sir 5 .B3 Lobby when door closing some noise issue" there is issue of door alignment I have told to supervisor for set by carpenter .									

Status History :	Date Time	Technician Name	Status		Remark	Sign
	19-04-2023 04:16:14	Atique Salmani	Comple	eted	Poonam cluster 1."B1 - 503 camera need to shift 1 meter can shift without new cabling client need boath qoute if new cabling then cable 35/40 meter 2.B2 Lobby 7-8 camera off issue 5th floor refuge area 504 side duct Poe switch plug point remooved . 3.Main gate biometric machine need to take in network in device rj 45 connector missing also need 5 meter cat6 cable 4.B2 P2 office outside camera angle need to change set angel according to Mateen sir 5.B3 Lobby when door closing some noise issue" there is issue of door alignment I have told to supervisor for set by carpenter .	
	19-04-2023 10:56:14	Atique New Salmani				-
Previous Complain	Date Time Technician		n Name	Remark		
History :	11-04-2023 05:17:24 Prashant N		Nikalje	Prashant visited on 11.04.2023 - Boom barrier remote control issued replace all remote battery now all remote working ok F parking boom barrier remote not working need to be changed		king ok P1
	18-03-2023 04:29:53 Prashant		Nikalje	B1 TV no signal issued reconnect hdmi and cat 6 cable		le