







# Vallabh Enterprises

Regd. Office : 401,shanti kutir,shivaji road,near thakur international school,kandivali(west) mumbai - 400067  
Support : | W : www.vallabhenterprises.com  
E : vallabhsecure@yahoo.co.in

<b>Service Status Details : VE10061</b>																																			
<b>Priority :</b>	Low																																		
<b>Created By :</b>	Admin - Apurva Vajaria																																		
<b>Complaint Mob. No. :</b>	9820242335																																		
<b>Technician Name :</b>	Sonu Kumar		<b>Technician Mobile :</b>	8454016444																															
<b>Ticket Type :</b>	Complain	<b>Date &amp; Time :</b>	17-11-2023 02:32:45																																
<b>Vendor Details :</b>																																			
Company Name/Client Name :	Shatrunjay Darshan Society	Customer's Mobile :	9820242335	Name :	Riyaz Sir																														
<b>Address :</b>																																			
Mumbai , , , , Maharashtra																																			
<b>AMC Details :</b>																																			
Expiry Date :	01-01-1970 05:30:00		Type :																																
<b>Product Name :</b>	CCTV																																		
<b>Complain :</b>	C wing lift camera not working																																		
<b>Technician Comment :</b>	Bike parking camera install working ok and c wing pump roop side camer off issue resolved working ok and 1 pair cable faulty white green																																		
<b>Complain Operator :</b>	Desktop - Apurva Vajaria																																		
<b>Remark :</b>	Bike parking camera install working ok and c wing pump roop side camer off issue resolved working ok and 1 pair cable faulty white green																																		
<b>Status History :</b>	<table><thead><tr><th>Date Time</th><th>Technician Name</th><th>Status</th><th>Remark</th><th>Sign</th></tr></thead><tbody><tr><td>03-12-2023 02:10:46</td><td>Sonu Kumar</td><td>Completed</td><td>Bike parking camera install working ok and c wing pump roop side camer off issue resolved working ok and 1 pair cable faulty white green</td><td></td></tr><tr><td>02-12-2023 06:10:31</td><td>Sonu Kumar</td><td>New</td><td></td><td>-</td></tr><tr><td>01-12-2023 11:02:54</td><td>Sonu Kumar</td><td>New</td><td></td><td>-</td></tr><tr><td>18-11-2023 12:26:14</td><td>Sonu Kumar</td><td>Work Pending</td><td>C wing lift transmetar adufter faulty and collect and old adufter install in client side all working ok and security cabin tv off issue resolved working ok</td><td></td></tr><tr><td>18-11-2023 10:19:04</td><td>Sonu Kumar</td><td>New</td><td></td><td>-</td></tr></tbody></table>					Date Time	Technician Name	Status	Remark	Sign	03-12-2023 02:10:46	Sonu Kumar	Completed	Bike parking camera install working ok and c wing pump roop side camer off issue resolved working ok and 1 pair cable faulty white green		02-12-2023 06:10:31	Sonu Kumar	New		-	01-12-2023 11:02:54	Sonu Kumar	New		-	18-11-2023 12:26:14	Sonu Kumar	Work Pending	C wing lift transmetar adufter faulty and collect and old adufter install in client side all working ok and security cabin tv off issue resolved working ok		18-11-2023 10:19:04	Sonu Kumar	New		-
Date Time	Technician Name	Status	Remark	Sign																															
03-12-2023 02:10:46	Sonu Kumar	Completed	Bike parking camera install working ok and c wing pump roop side camer off issue resolved working ok and 1 pair cable faulty white green																																
02-12-2023 06:10:31	Sonu Kumar	New		-																															
01-12-2023 11:02:54	Sonu Kumar	New		-																															
18-11-2023 12:26:14	Sonu Kumar	Work Pending	C wing lift transmetar adufter faulty and collect and old adufter install in client side all working ok and security cabin tv off issue resolved working ok																																
18-11-2023 10:19:04	Sonu Kumar	New		-																															

Previous Complain History :	Date Time	Technician Name	Remark
	07-12-2023 12:57:50		
	20-11-2023 04:50:26	Sonu Kumar	B wing lift 2 camera off issue solved B wing terrace camera off issue resolved C wing pump room side camera issue pending cable need to chk