




Vallabh Enterprises

Regd. Office : 401,shanti kutir,shivaji road,near thakur international school,kandivali(west) mumbai - 400067
Support : | W : www.vallabhenterprises.com
E : vallabhsecure@yahoo.co.in

Service Status Details : VE13855					
Priority :	Low				
Created By :	Admin - Apurva Vajaria				
Complaint Mob. No. :	9820242335				
Technician Name :	Pravin Jagade		Technician Mobile :	7262044153	
Ticket Type :	Complain	Date & Time :	18-01-2025 10:47:41		
Vendor Details :					
Company Name/Client Name :	Shatrunjay Darshan Society	Customer's Mobile :	9820242335	Name :	Riyaz Sir
Address :					
Mumbai , , , Maharashtra					
AMC Details :					
Expiry Date :	01-01-1970 05:30:00		Type :		
Product Name :	CCTV				
Complain :	lift cameras off issue				
Technician Comment :	Lift Camera issue resolved because lift power supply off issue and reon supply issue resoved and main gate cabin Camera ok cable issue need to Change Adpter wing Back side Camera issue camera take to office for checking				
Complain Operator :	Desktop - Apurva Vajaria				
Remark :	Lift Camera issue resolved because lift power supply off issue and reon supply issue resoved and main gate cabin Camera ok cable issue need to Change Adpter wing Back side Camera issue camera take to office for checking				

Status History :

Date Time	Technician Name	Status	Remark	Sign
03-04-2025 10:23:42	PravinJagade	New		-
19-03-2025 05:26:23	PravinJagade	Work Pending	Lift Camera issue resolved because lift power supply off issue and reon supply issue resoved and main gate cabin Camera ok cable issue need to Change Adpter wing Back side Camera issue camera take to office for checking	
19-03-2025 10:24:01	PravinJagade	New		-
17-03-2025 06:36:44	PravinJagade	New		-
21-02-2025 01:02:09	PravinJagade	New		-
19-02-2025 11:20:59	PravinJagade	New		-
07-02-2025 05:38:49	PravinJagade	Work Pending	1)Main gate camera and mandir camera offline because power issue camera collect check office. 2) B wing back side camera offline issue resolved connector change. 3) C wing lift 2 camera offline because lift socket falty / camera working. 4) B wing lift 1 camera offline / C wing lift 1 A wing lift camera offline because 2nd lift personal not coming. 5) teres camera falty power issue camera not install.	
07-02-2025 11:01:36	PravinJagade	New		-
06-02-2025 01:29:30	PravinJagade	New		-
20-01-2025 04:36:43	PravinJagade	Awaiting Spares	C wing terrace camera issue so collect for check and 1temple side 2 camera new cabling by electrician and one garbage area new cabling all crimping done and one a wing back side camera issue resolved working ok all only lifts cameras off .	
20-01-2025 12:07:42	PravinJagade	New		-

Previous Complain History :

Date Time	Technician Name	Remark
02-04-2025 01:22:26	PravinJagade	
03-02-2025 01:27:10	Siddhesh Chavan	Camera working ok