## Vallabh Enterprises

**Regd. Office** : 401, shanti kutir, shivaji road, near thakur international school, kandivali(west) mumbai - 400067 Support : | W : www.vallabhenterprises.com E : vallabhsecure@yahoo.co.in

Service Status Details : VE14671 Low **Priority** : **Created By :** Admin - Apurva Vajaria **Complaint Mob.** 9820242335 **No. : Technician Name** Neeraj Chauhan **Technician Mobile** 8898885764 : Complain 06-05-2025 11:34:31 **Ticket Type :** Date & Time : Vendor Details : Shatrunjay Customer's Mobile 9820242335 Riyaz Sir Company Name : Name/Client Name Darshan Society Address : Mumbai,,,, Maharashtra **AMC Details :** 01-01-1970 05:30:00 Expiry Date : Type : **Product Name :** CCTV **Complain**: turf area repaired camera need to install and to other camera also need to check Turf out side camera installation done security cabin camera not working temporary b wing Technician **Comment** : lobby camera sift to security Complain Desktop - Apurva Vajaria **Operator** : **Remark** : Turf out side camera installation done security cabin camera not working temporary b wing lobby camera sift to security **Status History : Date Time Technician Name** Status Remark Sign 06-05-2025 Neeraj Chauhan Completed Turf out side camera 03:56:48 installation done security cabin camera not working temporary b wing lobby camera sift to security 06-05-2025 Neeraj Chauhan New 11:34:42 Previous **Date Time Technician Name** Remark **Complain History** 02-04-2025 01:22:26 PravinJagade A wing lift no.2, C wing lobby, C wing pump room, C wing lift 1, C wing lift 2, B wing lift 1, B wing backside, C wing frontside , security cabin, all cameras issue resolved 03-02-2025 01:27:10 Siddhesh Chavan Camera working ok