




# Vallabh Enterprises

Regd. Office : 401,shanti kutir,shivaji road,near thakur international school,kandivali(west) mumbai - 400067  
Support : | W : www.vallabhenterprises.com  
E : vallabhsecure@yahoo.co.in

<b>Service Status Details : VE7247</b>																									
<b>Priority :</b>	Low																								
<b>Created By :</b>	Admin - Apurva Vajaria																								
<b>Complaint Mob. No. :</b>	9820242335																								
<b>Technician Name :</b>	Sonu Kumar		<b>Technician Mobile :</b>	8454016444																					
<b>Ticket Type :</b>	Complain	<b>Date &amp; Time :</b>	02-01-2023 02:11:34																						
<b>Vendor Details :</b>																									
Company Name/Client Name :	Shatrunjay Darshan Society	Customer's Mobile :	9820242335	Name :	Riyaz Sir																				
<b>Address :</b>																									
Mumbai , , , , Maharashtra																									
<b>AMC Details :</b>																									
Expiry Date :	01-01-1970 05:30:00		Type :																						
<b>Product Name :</b>	CCTV																								
<b>Complain :</b>	1 camera moisture issue																								
<b>Technician Comment :</b>	One cmaera fog issue resolved working ok and 3 camera angle setting done																								
<b>Complain Operator :</b>	Desktop - Apurva Vajaria																								
<b>Remark :</b>	One cmaera fog issue resolved working ok and 3 camera angle setting done																								
<b>Status History :</b>	<table><thead><tr><th>Date Time</th><th>Technician Name</th><th>Status</th><th>Remark</th><th>Sign</th></tr></thead><tbody><tr><td>03-01-2023 03:22:13</td><td>Sonu Kumar</td><td>Completed</td><td>One cmaera fog issue resolved working ok and 3 camera angle setting done</td><td></td></tr><tr><td>03-01-2023 10:22:09</td><td>Sonu Kumar</td><td>New</td><td></td><td>-</td></tr><tr><td>02-01-2023 02:11:44</td><td>Sonu Kumar</td><td>New</td><td></td><td>-</td></tr></tbody></table>					Date Time	Technician Name	Status	Remark	Sign	03-01-2023 03:22:13	Sonu Kumar	Completed	One cmaera fog issue resolved working ok and 3 camera angle setting done		03-01-2023 10:22:09	Sonu Kumar	New		-	02-01-2023 02:11:44	Sonu Kumar	New		-
Date Time	Technician Name	Status	Remark	Sign																					
03-01-2023 03:22:13	Sonu Kumar	Completed	One cmaera fog issue resolved working ok and 3 camera angle setting done																						
03-01-2023 10:22:09	Sonu Kumar	New		-																					
02-01-2023 02:11:44	Sonu Kumar	New		-																					
<b>Previous Complain History :</b>	<table><thead><tr><th>Date Time</th><th>Technician Name</th><th>Remark</th></tr></thead><tbody><tr><td>09-12-2022 05:25:18</td><td>MayurYadav</td><td></td></tr><tr><td>23-11-2022 11:03:58</td><td>Prashant Nikalje</td><td>1 camera not showing on display (No Link) decreasing framerate and bitrate D8-192.168.1.141 - Temple D wing side admin pass-Open, B wing lift no. 1 camera off, main supply on(lift) c wing lift no. 1 camera off need to check AP and client 26.11.2022 - Prashant/Dilshad visited the site : C wing lift 1 and b wing lift 1 camera off reconnect AP and client (transmitter and receiver both side) B wing lift AP side Power point issued 1 camera angle set (Opp office door side turf corner)</td></tr></tbody></table>					Date Time	Technician Name	Remark	09-12-2022 05:25:18	MayurYadav		23-11-2022 11:03:58	Prashant Nikalje	1 camera not showing on display (No Link) decreasing framerate and bitrate D8-192.168.1.141 - Temple D wing side admin pass-Open, B wing lift no. 1 camera off, main supply on(lift) c wing lift no. 1 camera off need to check AP and client 26.11.2022 - Prashant/Dilshad visited the site : C wing lift 1 and b wing lift 1 camera off reconnect AP and client (transmitter and receiver both side) B wing lift AP side Power point issued 1 camera angle set (Opp office door side turf corner)											
Date Time	Technician Name	Remark																							
09-12-2022 05:25:18	MayurYadav																								
23-11-2022 11:03:58	Prashant Nikalje	1 camera not showing on display (No Link) decreasing framerate and bitrate D8-192.168.1.141 - Temple D wing side admin pass-Open, B wing lift no. 1 camera off, main supply on(lift) c wing lift no. 1 camera off need to check AP and client 26.11.2022 - Prashant/Dilshad visited the site : C wing lift 1 and b wing lift 1 camera off reconnect AP and client (transmitter and receiver both side) B wing lift AP side Power point issued 1 camera angle set (Opp office door side turf corner)																							