Vallabh Enterprises

 $\label{eq:Regd.office:401,shanti kutir,shivaji road,near thakur international school,kandivali(west) mumbai - 400067 \\ \text{Support:} \mid \textbf{W}: www.vallabhenterprises.com \\ \textbf{E}: vallabhsecure@yahoo.co.in \\ \end{cases}$

Service Status De	tails: VE7477						
Priority:	Low						
Created By:	Admin - Apurva Vajaria						
Complaint Mob. No. :	9820242335						
Technician Name :	Atique Salmani		Technic:	ian Mobile 8080922984			
Ticket Type :	Complain Date & Time :		28-01-20	28-01-2023 12:26:37			
Vendor Details :	•						
Company Name/Client Name :	Shatrunjay Darshan Society	Customer's Mobile:	e 9820242	2335	Name :	Riyaz Sir	
Address:	•		•				
Mumbai , , , , Ma	harashtra						
AMC Details :							
Expiry Date :	01-01-1970 05:30:0	Type:	Type:				
Product Name:	CCTV						
Complain:	2 cameras offline						
Technician Comment :	1.Parking area one camera off re coonnect from camera end and working ok. 2 d wing lift camera SMPS was off top of lift on with lift security person akash and show to him dnt off this swich						
Complain Operator :	Desktop - Apurva Vajaria						
Remark :	1.Parking area one camera off re coonnect from camera end and working ok. 2 d wing lift camera SMPS was off top of lift on with lift security person akash and show to him dnt off this swich						
Status History :	Date Time	Technician Name	Status	Remark		Sign	
	03-02-2023 05:53:35	Atique Salmani	Closed			-	
	28-01-2023 02:47:12	Atique Salmani	Completed	re coonnect fro and working ol camera SMPS lift on with lift		9por	
	28-01-2023 12:26:57	Atique Salmani	New			-	

Previous Complain History:	Date Time	Technician Name	Remark	
	30-01-2023 01:58:17	Prashant Nikalje	All cameras offline issued restart all switch and NVR issue resolved	
	10-01-2023 10:51:18	Prashant Nikalje	Tv view at security cabin start Two camera off line issue pending 2 cameras offline issued cable short not getting continuity need to replace change cable 200 mtr Location temple side and pump room camera	