

Vallabh Enterprises

Regd. Office : 401,shanti kutir,shivaji road,near thakur international school,kandivali(west) mumbai - 400067
Support : | W : www.vallabhenterprises.com
E : vallabhsecure@yahoo.co.in

Service Status Details : VE14845																				
Priority :	Low																			
Created By :	Admin - Apurva Vajaria																			
Complaint Mob. No. :	9082608187																			
Technician Name :	Rahul Mhapralkar		Technician Mobile :	9168762949																
Ticket Type :	New Installation	Date & Time :	28-05-2025 12:27:13																	
Vendor Details :																				
Company Name/Client Name :	MAHAVIR SQUARE	Customer's Mobile :	9082608187	Name :	Rohit Sir															
Address :																				
Mumbai , , , , Maharashtra																				
AMC Details :																				
Expiry Date :	01-01-1970 05:30:00		Type :																	
Product Name :	VDP																			
Complain :	vdp installation need to do																			
Technician Comment :	B wing 1201 flat indoor unit to shaft cable damaged need to change A wing 1105,1905,402,506. Vdp installed																			
Complain Operator :	Desktop - Apurva Vajaria																			
Remark :	B wing 1201 flat indoor unit to shaft cable damaged need to change A wing 1105,1905,402,506. Vdp installed																			
Status History :	<table><thead><tr><th>Date Time</th><th>Technician Name</th><th>Status</th><th>Remark</th><th>Sign</th></tr></thead><tbody><tr><td>28-05-2025 02:10:14</td><td>Rahul Mhapralkar</td><td>Completed</td><td>B wing 1201 flat indoor unit to shaft cable damaged need to change A wing 1105,1905,402,506. Vdp installed</td><td></td></tr><tr><td>28-05-2025 12:27:26</td><td>Rahul Mhapralkar</td><td>New</td><td></td><td>-</td></tr></tbody></table>					Date Time	Technician Name	Status	Remark	Sign	28-05-2025 02:10:14	Rahul Mhapralkar	Completed	B wing 1201 flat indoor unit to shaft cable damaged need to change A wing 1105,1905,402,506. Vdp installed		28-05-2025 12:27:26	Rahul Mhapralkar	New		-
Date Time	Technician Name	Status	Remark	Sign																
28-05-2025 02:10:14	Rahul Mhapralkar	Completed	B wing 1201 flat indoor unit to shaft cable damaged need to change A wing 1105,1905,402,506. Vdp installed																	
28-05-2025 12:27:26	Rahul Mhapralkar	New		-																
Previous Complain History :	<table><thead><tr><th>Date Time</th><th>Technician Name</th><th>Remark</th></tr></thead><tbody><tr><td>25-07-2025 03:15:33</td><td>Rahul Mhapralkar</td><td></td></tr><tr><td>25-07-2025 12:19:06</td><td>Rahul Mhapralkar</td><td>Intercom calling issue resolved .8,5,2 floor power supply off issue resolved</td></tr></tbody></table>					Date Time	Technician Name	Remark	25-07-2025 03:15:33	Rahul Mhapralkar		25-07-2025 12:19:06	Rahul Mhapralkar	Intercom calling issue resolved .8,5,2 floor power supply off issue resolved						
Date Time	Technician Name	Remark																		
25-07-2025 03:15:33	Rahul Mhapralkar																			
25-07-2025 12:19:06	Rahul Mhapralkar	Intercom calling issue resolved .8,5,2 floor power supply off issue resolved																		