







# Vallabh Enterprises

**Regd. Office :** 401,shanti kutir,shivaji road,near thakur international school,kandivali(west) mumbai - 400067  
**Support : | W :** www.vallabhenterprises.com  
**E :** vallabhsecure@yahoo.co.in

<b>Service Status Details : VE15443</b>																									
<b>Priority :</b>	Low																								
<b>Created By :</b>	Admin - Apurva Vajaria																								
<b>Complaint Mob. No. :</b>	9082608187																								
<b>Technician Name :</b>	Rahul Mhapralkar		<b>Technician Mobile :</b>	9168762949																					
<b>Ticket Type :</b>	Complain	<b>Date &amp; Time :</b>	31-07-2025 10:37:26																						
<b>Vendor Details :</b>																									
Company Name/Client Name :	MAHAVIR SQUARE	Customer's Mobile :	9082608187	Name :	Rohit Sir																				
<b>Address :</b>																									
Mumbai , , , , Maharashtra																									
<b>AMC Details :</b>																									
Expiry Date :	01-01-1970 05:30:00		Type :																						
<b>Product Name :</b>	CCTV																								
<b>Complain :</b>	B 1303 VDP Query failed error - 7045957766																								
<b>Technician Comment :</b>	Outdoor Camera quarry failed issue resolved																								
<b>Complain Operator :</b>	Desktop - Apurva Vajaria																								
<b>Remark :</b>	Outdoor Camera quarry failed issue resolved																								
<b>Status History :</b>	<table><thead><tr><th>Date Time</th><th>Technician Name</th><th>Status</th><th>Remark</th><th>Sign</th></tr></thead><tbody><tr><td>31-07-2025 02:09:32</td><td>Rahul Mhapralkar</td><td>Completed</td><td>Outdoor Camera quarry failed issue resolved</td><td></td></tr><tr><td>31-07-2025 02:09:32</td><td>Rahul Mhapralkar</td><td>Completed</td><td>Outdoor Camera quarry failed issue resolved</td><td></td></tr><tr><td>31-07-2025 10:37:43</td><td>Rahul Mhapralkar</td><td>New</td><td></td><td>-</td></tr></tbody></table>					Date Time	Technician Name	Status	Remark	Sign	31-07-2025 02:09:32	Rahul Mhapralkar	Completed	Outdoor Camera quarry failed issue resolved		31-07-2025 02:09:32	Rahul Mhapralkar	Completed	Outdoor Camera quarry failed issue resolved		31-07-2025 10:37:43	Rahul Mhapralkar	New		-
Date Time	Technician Name	Status	Remark	Sign																					
31-07-2025 02:09:32	Rahul Mhapralkar	Completed	Outdoor Camera quarry failed issue resolved																						
31-07-2025 02:09:32	Rahul Mhapralkar	Completed	Outdoor Camera quarry failed issue resolved																						
31-07-2025 10:37:43	Rahul Mhapralkar	New		-																					
<b>Previous Complain History :</b>	<table><thead><tr><th>Date Time</th><th>Technician Name</th><th>Remark</th></tr></thead><tbody><tr><td>29-08-2025 10:38:36</td><td>Rahul Mhapralkar</td><td>B wing 2401 vdp calling issue resolved, B wing 1201 Vdp calling issue resolved, 1901 vdp calling issue resolved, A wing 1103 vdp installed,604 Vdp installed, A wing calling issue resolved, now A &amp; B intercom working normally</td></tr><tr><td>20-08-2025 10:33:47</td><td>Rahul Mhapralkar</td><td>1904 vdp out camera calling issue resolved now working normally.</td></tr></tbody></table>					Date Time	Technician Name	Remark	29-08-2025 10:38:36	Rahul Mhapralkar	B wing 2401 vdp calling issue resolved, B wing 1201 Vdp calling issue resolved, 1901 vdp calling issue resolved, A wing 1103 vdp installed,604 Vdp installed, A wing calling issue resolved, now A & B intercom working normally	20-08-2025 10:33:47	Rahul Mhapralkar	1904 vdp out camera calling issue resolved now working normally.											
Date Time	Technician Name	Remark																							
29-08-2025 10:38:36	Rahul Mhapralkar	B wing 2401 vdp calling issue resolved, B wing 1201 Vdp calling issue resolved, 1901 vdp calling issue resolved, A wing 1103 vdp installed,604 Vdp installed, A wing calling issue resolved, now A & B intercom working normally																							
20-08-2025 10:33:47	Rahul Mhapralkar	1904 vdp out camera calling issue resolved now working normally.																							