Vallabh Enterprises

 $\label{eq:Regd.office:401,shanti kutir,shivaji road,near thakur international school,kandivali(west) mumbai - 400067 \\ \text{Support:} \mid \textbf{W}: www.vallabhenterprises.com \\ \textbf{E}: vallabhsecure@yahoo.co.in \\ \end{cases}$

| L. vanabiisecure@yanoo.co.iii | | | | | | |
|----------------------------------|--|---------------------|---|--|--------|---------------|
| Service Status Details : VE14937 | | | | | | |
| Priority: | Low | | | | | |
| Created By: | Admin - Apurva Vajaria | | | | | |
| Complaint Mob. No. : | 932222599 | | | | | |
| Technician Name: | Ravi Rajbhar | | Technician Mobile 8080922965 | | | |
| Ticket Type : | Complain | Date & Time : | 06-06-2025 11:32:48 | | | |
| Vendor Details : | | | | | | |
| Company Name/Client Name : | DB Woods | Customer's Mobile : | 9322222599 | | Name : | Sandeep Saraf |
| Address: | | | | | | |
| Mumbai , , , , Maharashtra | | | | | | |
| AMC Details: | | | | | | |
| Expiry Date : | 01-01-1970 05:30 | Type: | | | | |
| Product Name: | automation | | | | | |
| Complain: | Sachit sir room some red light continue on issue | | | | | |
| Technician Comment : | Bd Wood 1204 autometion issue resolved and ok working done But sachit sir room red right pending bcx electian work | | | | | |
| Complain Operator : | Desktop - Apurva Vajaria | | | | | |
| Remark: | Bd Wood 1204 autometion issue resolved and ok working done But sachit sir room red right pending bcx electian work | | | | | |
| Status History: | Date Time | Technician Name | Status | Remark | | Sign |
| | 06-06-2025 06:02:02 | Ravi Rajbhar | Completed | Bd Wood 1204 autometion issue resolved and ok working done But sachit sir room red right pending bcx electian work | | |
| | 06-06-2025 11:33:18 | Ravi Rajbhar | New | | | - |
| Previous Complain History | Date Time Technician Name Remark | | | | | |
| : | 10-06-2025 10:24:3 | Ravi Rajbhar | Sachit sir room red light issue resolved and ok working and sofa side one seen careat | | | |
| | 03-03-2025 03:52:0 | 2 Ravi Rajbhar | Sachit sir bedroom automation issue resolved and ok working done gateway add with configuration done and all ok working | | | |