




# Vallabh Enterprises

**Regd. Office :** 401,shanti kutir,shivaji road,near thakur international school,kandivali(west) mumbai - 400067  
**Support :** | **W :** www.vallabhenterprises.com  
**E :** vallabhsecure@yahoo.co.in

<b>Service Status Details : VE1218</b>																														
<b>Priority :</b>	Low																													
<b>Created By :</b>	Admin - Apurva Vajaria																													
<b>Complaint Mob. No. :</b>	8291293893																													
<b>Technician Name :</b>	Atique Salmani		<b>Technician Mobile :</b>	8080922984																										
<b>Ticket Type :</b>	Complain	<b>Date &amp; Time :</b>	25-02-2020 04:24:23																											
<b>Vendor Details :</b>																														
<b>Company Name/Client Name :</b>	Peoples Gym - Modi Fitness Pvt Ltd	<b>Customer's Mobile :</b>	8291293893	<b>Name :</b>	Sandeep Sir																									
<b>Address :</b>																														
Mumbai , , , , Maharashtra																														
<b>AMC Details :</b>																														
<b>Expiry Date :</b>	01-01-1970 05:30:00		<b>Type :</b>																											
<b>Product Name :</b>	CCTV																													
<b>Complain :</b>	1 camera shifting confirm charges																													
<b>Technician Comment :</b>	one door access cable contie check and nmbring and installed one access 10 and also told to sultana mam how to add fp and cameras vewing issue also resolved but swich side cat 6 cable is too short so its need to changed.																													
<b>Complain Operator :</b>	Desktop - Apurva Vajaria																													
<b>Remark :</b>	one door access cable contie check and nmbring and installed one access 10 and also told to sultana mam how to add fp and cameras vewing issue also resolved but swich side cat 6 cable is too short so its need to changed.																													
<b>Status History :</b>	<table><thead><tr><th>Date Time</th><th>Technician Name</th><th>Status</th><th>Remark</th><th>Sign</th></tr></thead><tbody><tr><td>05-03-2020 04:25:56</td><td>Atique Salmani</td><td>Completed</td><td></td><td>-</td></tr><tr><td>27-02-2020 05:52:53</td><td>Atique Salmani</td><td>Client Side</td><td>one door access cable contie check and nmbring and installed one access 10 and also told to sultana mam how to add fp and cameras vewing issue also resolved but swich side cat 6 cable is too short so its need to changed.</td><td></td></tr><tr><td>27-02-2020 10:22:22</td><td>Atique Salmani</td><td>New</td><td></td><td>-</td></tr><tr><td>25-02-2020 04:24:24</td><td>Atique Salmani</td><td>New</td><td></td><td>-</td></tr></tbody></table>					Date Time	Technician Name	Status	Remark	Sign	05-03-2020 04:25:56	Atique Salmani	Completed		-	27-02-2020 05:52:53	Atique Salmani	Client Side	one door access cable contie check and nmbring and installed one access 10 and also told to sultana mam how to add fp and cameras vewing issue also resolved but swich side cat 6 cable is too short so its need to changed.		27-02-2020 10:22:22	Atique Salmani	New		-	25-02-2020 04:24:24	Atique Salmani	New		-
Date Time	Technician Name	Status	Remark	Sign																										
05-03-2020 04:25:56	Atique Salmani	Completed		-																										
27-02-2020 05:52:53	Atique Salmani	Client Side	one door access cable contie check and nmbring and installed one access 10 and also told to sultana mam how to add fp and cameras vewing issue also resolved but swich side cat 6 cable is too short so its need to changed.																											
27-02-2020 10:22:22	Atique Salmani	New		-																										
25-02-2020 04:24:24	Atique Salmani	New		-																										

<b>Previous Complain History :</b>	Date Time	Technician Name	Remark
	11-09-2020 09:57:48	Siddhesh Chavan	new power supply install and 4 camera video issue solved and 750 charges transfer to yash bhai
	08-08-2020 11:31:39	Siddhesh Chavan	dvr to router side crimping done and online view' ok and one camera video issue solved and One camera engel set and recoding show all camera working ok