




Vallabh Enterprises

Regd. Office : 401,shanti kutir,shivaji road,near thakur international school,kandivali(west) mumbai - 400067
Support : | W : www.vallabhenterprises.com
E : vallabhsecure@yahoo.co.in

Service Status Details : VE5455																									
Priority :	Low																								
Created By :	Admin - Apurva Vajaria																								
Complaint Mob. No. :	9167359050																								
Technician Name :	Atique Salmani		Technician Mobile :	8080922984																					
Ticket Type :	Complain	Date & Time :	14-05-2022 04:19:34																						
Vendor Details :																									
Company Name/Client Name :	Bombay Deyng And Manufacturing Co. Ltd	Customer's Mobile :	9167359050	Name :	Sandeep Sir																				
Address :																									
Mumbai , , , , Maharashtra																									
AMC Details :																									
Expiry Date :	31-07-2020 12:00:00		Type :	Comprehensive																					
Product Name :	CCTV																								
Complain :	one bullet camera need to change location HRC exit ground 40 MTR camera pinkish issue and 2 dome camera pinkish issue need to change																								
Technician Comment :	only one bullet camera changed HRC gate and old hand over to client new didn't installed becZ not covered whole camera .																								
Complain Operator :	Desktop - Apurva Vajaria																								
Remark :	only one bullet camera changed HRC gate and old hand over to client new didn't installed becZ not covered whole camera .																								
Status History :	<table><thead><tr><th>Date Time</th><th>Technician Name</th><th>Status</th><th>Remark</th><th>Sign</th></tr></thead><tbody><tr><td>14-05-2022 07:27:18</td><td>Atique Salmani</td><td>Completed</td><td>only one bullet camera changed HRC gate and old hand over to client new didn't installed becZ not covered whole camera .</td><td></td></tr><tr><td>14-05-2022 04:19:52</td><td>Atique Salmani</td><td>New</td><td></td><td>-</td></tr><tr><td>14-05-2022 04:19:34</td><td>Atique Salmani</td><td>New</td><td></td><td>-</td></tr></tbody></table>					Date Time	Technician Name	Status	Remark	Sign	14-05-2022 07:27:18	Atique Salmani	Completed	only one bullet camera changed HRC gate and old hand over to client new didn't installed becZ not covered whole camera .		14-05-2022 04:19:52	Atique Salmani	New		-	14-05-2022 04:19:34	Atique Salmani	New		-
Date Time	Technician Name	Status	Remark	Sign																					
14-05-2022 07:27:18	Atique Salmani	Completed	only one bullet camera changed HRC gate and old hand over to client new didn't installed becZ not covered whole camera .																						
14-05-2022 04:19:52	Atique Salmani	New		-																					
14-05-2022 04:19:34	Atique Salmani	New		-																					
Previous Complain History :	<table><thead><tr><th>Date Time</th><th>Technician Name</th><th>Remark</th></tr></thead><tbody><tr><td>20-05-2022 01:30:16</td><td>MayurYadav</td><td></td></tr><tr><td>19-05-2022 11:30:47</td><td>Shiva Meena</td><td>2 camera angal seting done and old camera pincesh issue continued, which needs replacement...noted</td></tr></tbody></table>					Date Time	Technician Name	Remark	20-05-2022 01:30:16	MayurYadav		19-05-2022 11:30:47	Shiva Meena	2 camera angal seting done and old camera pincesh issue continued, which needs replacement...noted											
Date Time	Technician Name	Remark																							
20-05-2022 01:30:16	MayurYadav																								
19-05-2022 11:30:47	Shiva Meena	2 camera angal seting done and old camera pincesh issue continued, which needs replacement...noted																							