







Vallabh Enterprises

Regd. Office : 401,shanti kutir,shivaji road,near thakur international school,kandivali(west) mumbai - 400067
Support : | W : www.vallabhenterprises.com
E : vallabhsecure@yahoo.co.in

Service Status Details : VE5459																														
Priority :	Low																													
Created By :	Admin - Apurva Vajaria																													
Complaint Mob. No. :	9167359050																													
Technician Name :	Atique Salmani		Technician Mobile :	8080922984																										
Ticket Type :	Complain	Date & Time :	14-05-2022 07:24:59																											
Vendor Details :																														
Company Name/Client Name :	Bombay Deyng And Manufacturing Co. Ltd	Customer's Mobile :	9167359050	Name :	Sandeep Sir																									
Address :																														
Mumbai , , , , Maharashtra																														
AMC Details :																														
Expiry Date :	31-07-2020 12:00:00		Type :	Comprehensive																										
Product Name :	CCTV																													
Complain :	6 cameras not working																													
Technician Comment :	2nd floor nort side SMPS off someone so it was off findout the spms and on its working all ok .																													
Complain Operator :	Desktop - Apurva Vajaria																													
Remark :	2nd floor nort side SMPS off someone so it was off findout the spms and on its working all ok .																													
Status History :	<table><thead><tr><th>Date Time</th><th>Technician Name</th><th>Status</th><th>Remark</th><th>Sign</th></tr></thead><tbody><tr><td>14-05-2022 07:41:22</td><td>Atique Salmani</td><td>Completed</td><td>2nd floor nort side SMPS off someone so it was off findout the spms and on its working all ok .</td><td></td></tr><tr><td>14-05-2022 07:31:38</td><td>Atique Salmani</td><td>Completed</td><td>only one bullet camera changed HRC gate and old hand over to client new didn't installed becz not covered whole camera .</td><td></td></tr><tr><td>14-05-2022 07:26:46</td><td>Atique Salmani</td><td>New</td><td></td><td>-</td></tr><tr><td>14-05-2022 07:24:59</td><td>Atique Salmani</td><td>New</td><td></td><td>-</td></tr></tbody></table>					Date Time	Technician Name	Status	Remark	Sign	14-05-2022 07:41:22	Atique Salmani	Completed	2nd floor nort side SMPS off someone so it was off findout the spms and on its working all ok .		14-05-2022 07:31:38	Atique Salmani	Completed	only one bullet camera changed HRC gate and old hand over to client new didn't installed becz not covered whole camera .		14-05-2022 07:26:46	Atique Salmani	New		-	14-05-2022 07:24:59	Atique Salmani	New		-
Date Time	Technician Name	Status	Remark	Sign																										
14-05-2022 07:41:22	Atique Salmani	Completed	2nd floor nort side SMPS off someone so it was off findout the spms and on its working all ok .																											
14-05-2022 07:31:38	Atique Salmani	Completed	only one bullet camera changed HRC gate and old hand over to client new didn't installed becz not covered whole camera .																											
14-05-2022 07:26:46	Atique Salmani	New		-																										
14-05-2022 07:24:59	Atique Salmani	New		-																										
Previous Complain History :	<table><thead><tr><th>Date Time</th><th>Technician Name</th><th>Remark</th></tr></thead><tbody><tr><td>14-05-2022 04:19:34</td><td>Atique Salmani</td><td>only one bullet camera changed HRC gate and old hand over to client new didn't installed becz not covered whole camera .</td></tr><tr><td>14-05-2022 10:24:36</td><td>Atique Salmani</td><td>12 volt 5 amps SMPS changed and access working ok.</td></tr></tbody></table>					Date Time	Technician Name	Remark	14-05-2022 04:19:34	Atique Salmani	only one bullet camera changed HRC gate and old hand over to client new didn't installed becz not covered whole camera .	14-05-2022 10:24:36	Atique Salmani	12 volt 5 amps SMPS changed and access working ok.																
Date Time	Technician Name	Remark																												
14-05-2022 04:19:34	Atique Salmani	only one bullet camera changed HRC gate and old hand over to client new didn't installed becz not covered whole camera .																												
14-05-2022 10:24:36	Atique Salmani	12 volt 5 amps SMPS changed and access working ok.																												