

Vallabh Enterprises

Regd. Office : 401,shanti kutir,shivaji road,near thakur international school,kandivali(west) mumbai - 400067
Support : | W : www.vallabhenterprises.com
E : vallabhsecure@yahoo.co.in

Service Status Details : VE3744																				
Priority :	Low																			
Created By :	Admin - Apurva Vajaria																			
Complaint Mob. No. :	"26773485																			
Technician Name :	Atique Salmani		Technician Mobile :	8080922984																
Ticket Type :	Complain	Date & Time :	31-08-2021 02:39:18																	
Vendor Details :																				
Company Name/Client Name :	Ashtavinayak Developers & Hospitality Pvt Ltd	Customer's Mobile :	"26773485	Name :	Sanjay															
Address :																				
Mumbai , , , , Maharashtra																				
AMC Details :																				
Expiry Date :	31-07-2020 12:00:00		Type :	Comprehensive																
Product Name :	Fire																			
Complain :	1st floor fire alarm issue + godrej lock issue																			
Technician Comment :																				
Complain Operator :	Desktop - Apurva Vajaria																			
Remark :																				
Status History :	<table><thead><tr><th>Date Time</th><th>Technician Name</th><th>Status</th><th>Remark</th><th>Sign</th></tr></thead><tbody><tr><td>31-08-2021 02:41:17</td><td>Atique Salmani</td><td>New</td><td></td><td>-</td></tr><tr><td>31-08-2021 02:39:18</td><td>Atique Salmani</td><td>New</td><td></td><td>-</td></tr></tbody></table>					Date Time	Technician Name	Status	Remark	Sign	31-08-2021 02:41:17	Atique Salmani	New		-	31-08-2021 02:39:18	Atique Salmani	New		-
Date Time	Technician Name	Status	Remark	Sign																
31-08-2021 02:41:17	Atique Salmani	New		-																
31-08-2021 02:39:18	Atique Salmani	New		-																

Previous Complain History :	Date Time	Technician Name	Remark
	28-08-2022 10:23:00	Atique Salmani	1.Fire ground floor issue resolved bynew connection from reception smoke detector . 2.And 108 washroom and bed room boath intercom issue resolved line ok phone not available . 3.208 boath intrcom working ok. 4.308 bedroom ok washroom cable need to changed from staircase junction to washroom 5.306 cable swap which one use not getting continuity so swap the other pair .boath working ok.also changed rj11 socket .South gate bullet need to changed And laundry dome need to changed Service lift 4th floor dome camera need to changed . 6.301 lock issue resolved by changed new battery 306 lock issue need to send in service center . 105 battery charged and also renew software.issue resolved . Lotus hall camera power drop so loop near camera for supply cable open lay 6 metr working ok . South gate bullet need to changed And laundry dome need to changed New camera mode didn't changed Service lift 4th floor dome camera need to changed . Terrace camera new installation done and Terrence camera installed near pool side . And bio matric machine collect for service center for chack .
	07-04-2022 02:41:13		online support- godrej locks pc software install done