

# Vallabh Enterprises

**Regd. Office :** 401,shanti kutir,shivaji road,near thakur international school,kandivali(west) mumbai - 400067  
**Support : | W :** www.vallabhenterprises.com  
**E :** vallabhsecure@yahoo.co.in

<b>Service Status Details : VE3745</b>																				
<b>Priority :</b>	Low																			
<b>Created By :</b>	Admin - Apurva Vajaria																			
<b>Complaint Mob. No. :</b>	"26773485																			
<b>Technician Name :</b>	Atique Salmani		<b>Technician Mobile :</b>	8080922984																
<b>Ticket Type :</b>	Complain	<b>Date &amp; Time :</b>	31-08-2021 02:41:00																	
<b>Vendor Details :</b>																				
<b>Company Name/Client Name :</b>	Ashtavinayak Developers & Hospitality Pvt Ltd	<b>Customer's Mobile :</b>	"26773485	<b>Name :</b>	Sanjay															
<b>Address :</b>																				
Mumbai , , , , Maharashtra																				
<b>AMC Details :</b>																				
<b>Expiry Date :</b>	31-07-2020 12:00:00		<b>Type :</b>	Comprehensive																
<b>Product Name :</b>	Ppm																			
<b>Complain :</b>	CCTV/EPABX/PA/Fire/Access																			
<b>Technician Comment :</b>																				
<b>Complain Operator :</b>	Desktop - Apurva Vajaria																			
<b>Remark :</b>																				
<b>Status History :</b>	<table><thead><tr><th>Date Time</th><th>Technician Name</th><th>Status</th><th>Remark</th><th>Sign</th></tr></thead><tbody><tr><td>31-08-2021 02:41:13</td><td>Atique Salmani</td><td>New</td><td></td><td>-</td></tr><tr><td>31-08-2021 02:41:00</td><td>Atique Salmani</td><td>New</td><td></td><td>-</td></tr></tbody></table>					Date Time	Technician Name	Status	Remark	Sign	31-08-2021 02:41:13	Atique Salmani	New		-	31-08-2021 02:41:00	Atique Salmani	New		-
Date Time	Technician Name	Status	Remark	Sign																
31-08-2021 02:41:13	Atique Salmani	New		-																
31-08-2021 02:41:00	Atique Salmani	New		-																

Previous Complain History :			
	<b>Date Time</b>	<b>Technician Name</b>	<b>Remark</b>
	28-08-2022 10:23:00	Atique Salmani	1.Fire ground floor issue resolved bynew connection from reception smoke detector . 2.And 108 washroom and bed room boath intercom issue resolved line ok phone not available . 3.208 boath intrcom working ok. 4.308 bedroom ok washroom cable need to changed from staircase junction to washroom 5.306 cable swap which one use not getting continuity so swap the other pair .boath working ok.also changed rj11 socket .South gate bullet need to changed And laundry dome need to changed Service lift 4th floor dome camera need to changed . 6.301 lock issue resolved by changed new battery 306 lock issue need to send in service center . 105 battery charged and also renew software.issue resolved . Lotus hall camera power drop so loop near camera for supply cable open lay 6 metr working ok . South gate bullet need to changed And laundry dome need to changed New camera mode didn't changed Service lift 4th floor dome camera need to changed . Terrace camera new installation done and Terrence camera installed near pool side . And bio matric machine collect for service center for chack .
	07-04-2022 02:41:13		online support- godrej locks pc software install done