## Vallabh Enterprises

**Regd. Office** : 401, shanti kutir, shivaji road, near thakur international school, kandivali(west) mumbai - 400067 Support : | W : www.vallabhenterprises.com E : vallabhsecure@yahoo.co.in

Service Status Details : VE10071 Low **Priority** : **Created By :** Admin - Apurva Vajaria **Complaint Mob.** 9325275974 **No. : Technician Name** Sonu Kumar **Technician Mobile** 8454016444 Complain 20-11-2023 10:14:44 **Ticket Type :** Date & Time : **Vendor Details :** Rahul International Customer's Mobile 9325275974 Sanjeet Sir Company Name : School - Boisar Name/Client Name Address : Mumbai, boisar WEST, , 401501, Maharashtra **AMC Details :** 01-01-1970 05:30:00 Expiry Date : Type : **Product Name :** CCTV **Complain**: A wing Ground floor and B wing 1st and 2nd floor On tv cameras not able to see 60 MTR hdmi extendar and 4port hdmi switcher Recruitment in sanjeet sir Technician **Comment**: Complain Desktop - Apurva Vajaria **Operator** : **Remark** : 60 MTR hdmi extendar and 4port hdmi switcher Recruitment in sanjeet sir **Status History : Technician Name Date Time** Status Remark Sign 30-11-2023 12:15:10 Sonu Kumar Completed 60 MTR hdmi extendar and 4port hdmi switcher Recruitment in sanjeet sir 30-11-2023 10:27:52 Sonu Kumar New 22-11-2023 06:08:52 Sonu Kumar New **Previous Date Time Technician Name** Remark **Complain History** 09-12-2023 PravinJagade All device getting online and system check. 09:14:10 07-11-2023 InzmamUl Haq All devices online A wing 1 st flr 102 cam pinkish issue solved 10:24:01 A wing 2nd flr library blur issue not resolved A wing 3rd flr 308 camera pinkish issue not resolved A wing 3rd flr washroom area black /white issue solved A wing 3rd flr b wing pass facing camera not working A wing 3rd flr passage camera not working 1 pair video bolun