




# Vallabh Enterprises

**Regd. Office :** 401,shanti kutir,shivaji road,near thakur international school,kandivali(west) mumbai - 400067  
**Support : | W :** www.vallabhenterprises.com  
**E :** vallabhsecure@yahoo.co.in

<b>Service Status Details : VE4899</b>																														
<b>Priority :</b>	Low																													
<b>Created By :</b>	Admin - Apurva Vajaria																													
<b>Complaint Mob. No. :</b>	9821745351																													
<b>Technician Name :</b>	Atique Salmani		<b>Technician Mobile :</b>	8080922984																										
<b>Ticket Type :</b>	New Installation	<b>Date &amp; Time :</b>	28-02-2022 12:45:03																											
<b>Vendor Details :</b>																														
<b>Company Name/Client Name :</b>	Swims Technologies Pvt Ltd	<b>Customer's Mobile :</b>	9821745351	<b>Name :</b>	Sanjeev Kabani																									
<b>Address :</b>																														
Mumbai , , , , Maharashtra																														
<b>AMC Details :</b>																														
<b>Expiry Date :</b>	01-01-1970 05:30:00		<b>Type :</b>																											
<b>Product Name :</b>	CCTV																													
<b>Complain :</b>	CCTV survey																													
<b>Technician Comment :</b>	One camera off 2 cameras pinkish need to changed and also cmos battery Dvr date n time issue Fire 2 zone pannel system ok 10 sd. 1 MCP 1 hooter Epbax .Panasonic kx-TES824 Line ok all dial tone getting Instrument need to installed 2 door access working ok boath dvr end need to dress .																													
<b>Complain Operator :</b>	Desktop - Apurva Vajaria																													
<b>Remark :</b>	One camera off 2 cameras pinkish need to changed and also cmos battery Dvr date n time issue Fire 2 zone pannel system ok 10 sd. 1 MCP 1 hooter Epbax .Panasonic kx-TES824 Line ok all dial tone getting Instrument need to installed 2 door access working ok boath dvr end need to dress .																													
<b>Status History :</b>	<table><thead><tr><th>Date Time</th><th>Technician Name</th><th>Status</th><th>Remark</th><th>Sign</th></tr></thead><tbody><tr><td>02-03-2022 12:09:31</td><td>Atique Salmani</td><td>Completed</td><td>One camera off 2 cameras pinkish need to changed and also cmos battery Dvr date n time issue Fire 2 zone pannel system ok 10 sd. 1 MCP 1 hooter Epbax .Panasonic kx-TES824 Line ok all dial tone getting Instrument need to installed 2 door access working ok boath dvr end need to dress .</td><td></td></tr><tr><td>02-03-2022 10:57:18</td><td>Atique Salmani</td><td>New</td><td></td><td>-</td></tr><tr><td>28-02-2022 12:45:18</td><td>Atique Salmani</td><td>New</td><td></td><td>-</td></tr><tr><td>28-02-2022 12:45:03</td><td>Atique Salmani</td><td>New</td><td></td><td>-</td></tr></tbody></table>					Date Time	Technician Name	Status	Remark	Sign	02-03-2022 12:09:31	Atique Salmani	Completed	One camera off 2 cameras pinkish need to changed and also cmos battery Dvr date n time issue Fire 2 zone pannel system ok 10 sd. 1 MCP 1 hooter Epbax .Panasonic kx-TES824 Line ok all dial tone getting Instrument need to installed 2 door access working ok boath dvr end need to dress .		02-03-2022 10:57:18	Atique Salmani	New		-	28-02-2022 12:45:18	Atique Salmani	New		-	28-02-2022 12:45:03	Atique Salmani	New		-
Date Time	Technician Name	Status	Remark	Sign																										
02-03-2022 12:09:31	Atique Salmani	Completed	One camera off 2 cameras pinkish need to changed and also cmos battery Dvr date n time issue Fire 2 zone pannel system ok 10 sd. 1 MCP 1 hooter Epbax .Panasonic kx-TES824 Line ok all dial tone getting Instrument need to installed 2 door access working ok boath dvr end need to dress .																											
02-03-2022 10:57:18	Atique Salmani	New		-																										
28-02-2022 12:45:18	Atique Salmani	New		-																										
28-02-2022 12:45:03	Atique Salmani	New		-																										

**Previous  
Complain  
History :**

**Date Time**

**Technician Name**

**Remark**